



NARRATIVE REPORT FORM

Facility Name: Glenwood Drive & Walker Road Primary Facility ID: 881609

Inspection Date: April 16, 2026		Inspection Time: 8:48 to 12:50		Lat/Long: 40.27076, -74.87578	
Inspecting Program:		<input type="checkbox"/> Storage Tanks	<input type="checkbox"/> HSCA	<input checked="" type="checkbox"/> LRP	
Owner Name:		Inspection Number: Not Applicable		Site ID: 881609	
Facility Location (911) Address: Walker Road, Glenwood Drive, & Spencer Road Washington Crossing, PA 18977			Municipality: Upper Makefield Township		
			County: Bucks County		
Responsible Official Name: Bradford Fish Responsible Official Title: Senior Environmental Specialist Emergency Response & Remediation			Responsible Official Address: 100 Green Street Marcus Hook, PA 19061		
Responsible Official Telephone: 610-859-6297					
Responsible Email: bradford.fish@energytransfer.com					

Narrative:

- Purpose of visit: Observe installation of monitoring wells along Glenwood Drive.
- Weather: Sunny to Overcast; 80s to 90s
- Crews onsite: Energy Transfer/Sunoco; GES, Stantec; Environmental Noise Control; Summit Drilling; Anson Construction
- 8:48 – DEP onsite. Drill crew not onsite yet.
- 8:53 – Summit onsite with drill rig and support trucks. After speaking with ET, the plan is to start installing the steel casing at the Well C location that was hand cleared yesterday then do the same at the Well B location.
- 9:15 – Summit begins setting the rig on Well C. Once the rig is in place, additional sound barriers are planned to be put up in between the rig and the property at [REDACTED].
- 9:31 – Drill rig set up and positioned on Well C.
- 9:35 – Decision made by ET to no add any additional sound barriers between [REDACTED] and the drill rig. ET did not want to have to move the drill rig again and said the hole will be done quickly. Additionally, ET felt that the additional barriers would be a safety hazard since Summit needs room on that side of the rig to access tooling.
- 10:15 – ET begins inspecting RW-2 with a camera to observe the condition of the borehole below the steel casing.
- 10:26 – Summit begins drilling Well C via air rotary.

DEP Representative Name Matthew Sabetta, P.G.	DEP Representative Signature Matthew Sabetta <small>Digitally signed by Matthew Sabetta Date: 2026.04.16 15:49:31 -04'00'</small>	Title Geologist	Date: April 16, 2026 Telephone: 484-250-5788
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Name of Person Interviewed Not applicable	Signature of Person Interviewed Not applicable	Title Not applicable	Date: Not applicable Telephone: Not applicable



NARRATIVE REPORT FORM

Facility Name: Glenwood Drive & Walker Road Primary Facility ID: 881609

- 10:30 – Drilling hits 5ft below ground surface. Dust began picking up. Drilling is stopped to hook up water for dust suppression while drilling.
- 10:40 – Drilling is resumed after hooking up water.
- 11:00 – Drilling reaches 10ft below ground surface. Competent rock began around 7ft below ground surface. No PID readings or odors were observed. ET is going to put a camera down the hole then Summit will set 6in steel casing to 10ft.
- 11:27 – ET completes camera inspection of the Well C borehole. No impacts or significant observations were noted by ET. Dave from EDN onsite to see how things are going. Summit now begins setting the steel casing.
- 11:53 – The casing is in the ground. Sand is used to seal the inside of casing instead of a plug.
- 12:25 – The casing is grouted in place. Grout consisted of Portland cement and bentonite. The grout was added via tremie pipe. Summit begins cleaning up for the day. No additional drilling will occur today.
- 12:40 – First load of equipment and drums heading to storage area near the job trailer. Confirmed with ET that the drill rig will stay on the hole overnight and will not be moved. They are planning on opening up the other side of the road by removing the sound barriers.
- 12:50 – DEP offsite.

DEP Representative Name Matthew Sabetta, P.G.	DEP Representative Signature Matthew Sabetta <small>Digitally signed by Matthew Sabetta Date: 2026.04.16 15:49:47 -04'00'</small>	Title Geologist	Date: April 16, 2026 Telephone: 484-250-5788
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Name of Person Interviewed Not applicable	Signature of Person Interviewed Not applicable	Title Not applicable	Date: Not applicable Telephone: Not applicable




NARRATIVE REPORT FORM


Facility Name: Glenwood Drive & Walker Road Primary Facility ID: 881609

MAPS / PHOTOGRAPHS / ATTACHMENTS

Aerial Image of Site Area (source: Google Earth)



Map showing general well installation area (source: April 22, 2025 Recovery Well Installation Work Plan)



DEP Representative Name Matthew Sabetta, P.G.	DEP Representative Signature Matthew Sabetta <small>Digitally signed by Matthew Sabetta Date: 2025.04.16 15:50:07 -04'00'</small>	Title Geologist	Date: April 16, 2026 Telephone: 484-250-5788
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Name of Person Interviewed Not applicable	Signature of Person Interviewed Not applicable	Title Not applicable	Date: Not applicable Telephone: Not applicable



NARRATIVE REPORT FORM

Facility Name: Glenwood Drive & Walker Road

Primary Facility ID: 881609



Drill rig setup on Well C.



Drill rig setup on Well C looking toward Walker Road.



Rock chips brought up from around 5ft below ground surface.



Borehole camera inspection completed by ET.

DEP Representative Name Matthew Sabetta, P.G.	DEP Representative Signature Matthew Sabetta <small>Digitally signed by Matthew Sabetta Date: 2026.04.16 15:50:23 -04'00'</small>	Title Geologist	Date: April 16, 2026 Telephone: 484-250-5788
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Name of Person Interviewed Not applicable	Signature of Person Interviewed Not applicable	Title Not applicable	Date: Not applicable Telephone: Not applicable

NARRATIVE REPORT FORM

Facility Name: Glenwood Drive & Walker Road Primary Facility ID: 881609



DEP Representative Name Matthew Sabetta, P.G.	DEP Representative Signature Matthew Sabetta <small>Digitally signed by Matthew Sabetta Date: 2026.04.16 15:50:41 -04'00'</small>	Title Geologist	Date: April 16, 2026 Telephone: 484-250-5788
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Name of Person Interviewed Not applicable	Signature of Person Interviewed Not applicable	Title Not applicable	Date: Not applicable Telephone: Not applicable