



NARRATIVE REPORT FORM

Facility Name: Glenwood Drive & Walker Road

Primary Facility ID: 881609

Inspection Date: 4/17/2026		Inspection Time: 09:35 – 12:45		Lat/Long: 40.27076, -74.87578	
Program:		<input type="checkbox"/> Storage Tanks		<input type="checkbox"/> HSCA	
				<input checked="" type="checkbox"/> LRP	
Owner Name: N/A			Inspection ID: N/A		Site ID: 881609
Facility Location (911) Address: Glenwood Drive between Walker Road and Spencer Road, Washington Crossing, PA 18977				Municipality: Upper Makefield Township	
				County: Bucks	
Responsible Official Name: Bradford Fish Title: Senior Environmental Specialist, Emergency Response & Remediation				Responsible Official Address: 100 Green Street Marcus Hook, PA 19061	
Responsible Official Telephone: 610-859-6297					
Email Address: bradford.fish@energytransfer.com					
Entities Present at Site:					
<ul style="list-style-type: none"> • Energy Transfer, LP – Chris Embry, Bill Barth, Wassim Saad, Joe Massaro • Groundwater & Environmental Services, Inc. – Mike Haezebrouck • Summit Drilling, LLC (Drilling Subcontractor) • Ansen Construction (Traffic Control Subcontractor) • Environmental Noise Control (Sound Monitoring/Barrier Subcontractor) • Stantec (Air Monitoring Subcontractor) • Earth Data Northeast, Inc. – Dave Fennimore (Upper Makefield Township Consultant) 					
Inspection Purpose: Observe Drilling of "Well C" near the intersection of Glenwood Drive and Walker Road, Washington Crossing, PA 18977 (Photo #1).					
Weather: Sunny, 80s °F					
PADEP Staff Present: Dustin Lipik, P.G. (DL)					
Narrative:					
<p>At 9:35, DL arrived at the work area near the intersection of Glenwood Drive and Walker Road. Summit Drilling, LLC (Summit) was in the process of advancing tooling into "Well C". Energy Transfer, LP (ET) and Groundwater & Environmental Services, Inc. (GES) staff were observing borehole advancement. Ansen Construction staff were providing traffic control and managing the exclusion zone. Environmental Noise Control and Stantec staff were providing noise and air monitoring, respectively. GES staff were also conducting routine total fluids removal activities at recovery well RW-2 and collecting groundwater elevation measurements from potable wells near the drilling area.</p> <p>At 9:45, DL speaks with Chris Embry (CE) of ET. CE tells DL that 10 feet (ft) of 6" steel casing from ground surface to 10 ft below ground surface (bgs) was installed on Thursday, April 16. Today, Summit has drilled a 4" diameter open borehole from 10 ft bgs to 40 ft bgs and is still advancing tooling. Wassim Saad (WS) and Bill Barth (BB) of ET are also on present at the drilling area. Dave Fennimore (DF) of Earth Data Northeast, Inc. (EDN), Upper Makefield Township's environmental consultant, arrives around this time to observe drilling activities.</p> <p>At 10:00, borehole reaches target depth of 65 ft bgs. Summit crew breaks to observe flow of water into borehole. DL speaks with Mike Haezebrouck (MH) of GES. MH indicates that photoionization detector (PID) readings collected every 5 ft from the borehole cuttings were all less than 0.5 parts per million (PPM). No odors were noted during drilling.</p> <p>At 10:47, Summit restarts rig and begins blowing out borehole to clear fines. Joe Massaro (JM) of ET arrives at site to provide drinks to work crews.</p>					



NARRATIVE REPORT FORM

Page 2 of 3

Between 10:53 and 11:05, Summit finishes borehole blowout and trips tooling out of borehole. BB of ET prepares equipment for ultraviolet (UV) logging of borehole.

Between 11:15 and 11:45, DL off site for lunch.

At 11:45, DL returns to drilling area. Summit crew is moving equipment from "Well C" to "Well B", located ~20 ft north of "Well C". BB of ET is in the process of evaluating "Well C" borehole with both UV and standard white light. DL confirms with CE and MH that the plan for the remainder of the day is to install steel casing to approximately 10 ft bgs at location "Well B".

At 12:40, BB finishes UV logging.

At 12:45, DL leaves Site.

NARRATIVE REPORT FORM

Facility Name: Glenwood Drive & Walker Road Primary Facility ID: 881609

PHOTOGRAPHS



Photo #1
 "Well C" Location, Washington Crossing, PA

DEP Representative Name Dustin Lipik, P.G.	DEP Representative Signature Dustin A. Lipik, P.G. <small>Digitally signed by Dustin A. Lipik, P.G. Date: 2026.04.20 15:04:52 -04'00'</small>	Title Licensed Professional Geologist	Date: 4/17/2026
			Phone: 484-250-5795