# Module 7: Geology Information [§77.403-404]

#### 7.1 Stratigraphy.

a) Rock Unit: Period (e.g., Lower Ordovician) Pennsylvanian - Freeport Formation

Formation (e.g., Rockdale Run) Freeport Sandstone

See the attached Exhibit 7.1a) Geologic column of the Freeport Formation

b) Attach Geologic Logs of test holes or equivalent information on attached data sheet (test holes should be drilled to the ultimate depth of mining unless waived by the Department based on acceptable equivalent information). Log description must include the surface elevation of each hole submitted, lowest elevation of proposed excavation, elevation of static groundwater (method and date of measurement), lithologic description, location and extent of voids and thickness of strata encountered. Drill holes, highwall sections, or equivalent information should be located to represent the thickness of mineral and overburden to be disturbed in areas of maximum thickness.

Drilling at the proposed site was completed in June 2021 and conducted by Preferred Drilling. A total of eight (8) holes were drilled within the proposed mining area. The holes were drilled through the Freeport Sandstone proposed for mining and into the underlying material. The drill hole locations were surveyed by Earthtech, Inc. for elevation and map placement on the Exhibit 6.2 Map. See the attached Module 7.1(B) Geologic Logs and the following chart summarizing the drilling information.

Drill Hole	Surface Elev. (ft.)	Bottom of Freeport Sand Elev. (ft.)	Freeport Sandstone Thickness (ft.)
RS-1	2031.4	1984.6	41.3
RS-2	2045.7	1994.8	46.9
RS-3	2108.6	2037.0	67.4
RS-4	2080.4	2006.6	69.9
RS-5	2127.2	2051.6	71.2
RS-6	2094.7	2011.9	79.5
RS-7	2118.7	2055.7	60.0
RS-8	2058.8	2008.8	41.7

c) Provide stratigraphic correlation of the strata by geologic cross sections or fence diagrams to include lithology, stratigraphy, existing ground surface, proposed mining limits, proposed benching, final reclamation slopes, postmining water table, aquifers to be encountered or affected, directions of groundwater movement and underground mines and cave systems. [Horizontal scale shall not be smaller than the scale of Exhibit 6.2 (i.e. not less than 1 inch:400 feet, or 1 inch:200 feet), larger scales are acceptable (e.g. 1 inch:100 feet)]

See the attached Exhibit (7.1c) Geologic Cross-Sections for cross-sections A-A' to B-B' through the proposed permit mining area. Stratigraphy was derived from on-site data. The cross-section lines are shown on the attached Exhibit 6.2 Map. Proposed post mining final reclamation slopes are shown in addition to water aquifer data. The post mining water table is anticipated to remain as it is pre-mining. Please refer to 7.4 for the known underground mines in or within 1,000 feet of the Rockwood Quarry site.

#### 7.2 Structure.

a) Describe the local geologic structure and its relationship to the regional structure. Use diagrams and regional structural relief maps where applicable.

The proposed mining area for the Rockwood Quarry is situated in the Allegheny Mountain Section of the Appalacian Plateaus Province. The sedimentary strata in this area of the province has been folded to varying degrees by a series of anticlines and synclines. The general orientation of the fold axes are in the southwest-northeast direction. Low magnitude and broad folds dominate this region, with higher degree folds associated with the ridge lines in the area of the Rockwood Quarry. The site is situated on the western flank of the Negro Mountain Anticline, approximately 4 miles west of the axis. The dip of the regional strata is northwesterly and the axis of the fold trends in a northeasterly direction of approximately N 45° E. See Exhibit 7.2a) Geologic Map of The Southern Half of Somerset County, Pennsylvania.

The sandstone proposed for mining is within the Freeport Formation and Pennsylvanian in age. The local geologic structure was derived from the drill hole data included with this module, and the original small/non-coal permit application. Like the regional structure, the local structure of the Freeport Sandstone also dips to the northwest away from the Negro Mountain Anticline. The Freeport Sandstone averages a N 48° E strike and a 7.1° (3.2%) NW dip. Measurements were obtained using the drill holes provided. See Exhibit 6.2 Map for local geologic structure.

7.3 Indicate joint and fracture orientations on the Module 6.2 map (or Module 6.1 if locations not within limits of Module 6.2), using standard joint strike and dip symbols, where fracture/joint measurements were taken. Rose diagrams may be submitted if available.

Type of Joint	Lithology	Number of	Depth Below	Aperature	Key to 6.2
Or Fracture*		Measurements	Surface	(width)	(or 6.1)
Stress Relief	Lower Worthington	2	At Surface_	Closed at depth	6.2

<sup>\*</sup>Type of Joint or Fracture refers to tectonic, stress relief, bedding plane, etc.

Source of information (site specific measurements, publication source, etc.) The stress relief joints and fractures listed above were measured at exposed outcropping along the walking trail adjacent to the Rockwood Quarry. The average readings were N 42°E and N 27°W.

NOTE: Operations in karst geology areas may be required to complete the *Karst Permitting Supplement* in addition to supplying this information.

7.1(B)	GEO	LOGIC L	.OG DRIL	L HOLES/OVERBURDEN AN	ALYSIS DATA	A			Page	1 of
	o.;				Operation Nar	me:				
(Ke	ey locatio	ons to Mo	dules 6.2 a	nd 9)	Method of Dril	ling:				
Bottom	Elevation	ns:			Drilled By:					
					Logged By: _					
Ground	water Ele	evations :	and Date M	easured	Township:					
Giodila	Water Lit	Evalions	and Date M							
					Quadrangle:					
Surveye	ed by:			======================================	Laboratory: _	0 ,	Lor	ngitude:	0	, , , , , , ,
								· –		
						Ove	rburden Analy	/sis Logs*		
					Color or	ОВА		%		
Depth	Thick- ness	Scale	Graphic Log	Lithologic Description and Water Conditions	Munsell Code	Sample Number	Log Interval	Total Sulfur	Fizz Rating	Neutralization Potential
	11000	:= =:								***************************************
		1 2								ĺ
				See the attached Module						- 1
		= =		7.1(B) geologic logs for the 8 holes drilled at the						- 1
		1 1		Rockwood Quarry site.						1
		i <del>−</del> 10 −		•						
		E E								1
		= =								
		= =								
		-								
		_ 20 _								
		-								
		9 . 7								
		_ 30 _								
		= =								
		Ī Ī								
		<u> 40                                   </u>								
		0 1								
		50 -								
		= =								
		_ 50 _								
		= (=								
		60 -								
		<u> </u>								
		= =								
		- 70								
		/V								

<sup>\*</sup>When requested by the Department

#### 7.4 Mine Workings and Solid Waste Sites.

Submit the following data on all active, completed and abandoned underground and surface mines and coal refuse disposal sites which are in or within 1000 feet of the permit area: (Key location to Modules 6.2, 9 and 18.)

Surface and Underground Mines

Operator	Permit No.	Map Key	Status	Mineral	Water Sample No.(s)
Rockwood Stone, LLC	56190801	Α	Existing	Freeport Sandstone	N/A
Penelec Coal	Unknown	В	Abandoned	Lower Kittanning Coal	3, 4
Unknown Punch Mine	Unknown	С	Abandoned	Lower Kittanning Coal	13

List the operator permit number, and type of any solid waste disposal sites in or within 1000 feet of the permit area.

There are no known solid waste disposal sites in or within 1,000 feet of the permit area.

#### 7.5 Overburden Analysis.

Note: Typically overburden analysis is not required for noncoal mining operations. However, there are geologic conditions that may make overburden analysis necessary due to the potential for surface and/or groundwater pollution. Examples are mines in coal field strata that may be acid-forming, and sites where rock has undergone sulfide mineralization. The necessity for overburden analysis should be determined prior to permit application submittal. This can be done by contacting the appropriate District Mining Office.

The interpretation of overburden analysis should be provided in this Module. However, the operational plans for material placement should be provided in Module 10.

#### a) Overburden Analysis Report

The overburden analysis report must include at a minimum:

- 1) Geologic logs of overburden analysis test holes including Munsell color codes. This must include the information requested in Module 7.1b. Overburden holes must be logged by a geologist. Water condition information is the same as that requested in Module 7.1b. This information is to be presented on a completed Module 7.1(B) "Geologic Log Drill Holes/ Overburden Analysis Data."
- 2) An explanation of considerations employed in determining
  - aa) drill hole spacing and number of holes,
  - bb) sampling depth; and
  - cc) sampling intervals of overburden analysis test holes.
- 3) A series of stratigraphic cross-sections or fence diagrams including all overburden analysis test holes, plus other representative test holes. The vertical scale must be sufficient to show all potentially acidic and alkaline zones and any zones proposed for special handling; a scale of one (1) inch to twenty (20) feet or greater is recommended. The stratigraphic correlations between overburden holes and other test holes must be shown. In addition, hydrogeologic information (such as water table, perched systems and so forth) should be portrayed.
- 4) Overburden holes accurately located on Exhibit 6.2. Overburden holes must be surveyed such that surface elevations and hole locations are accurately determined and plotted.

- 5) Results of the chemical analysis of all overburden strata and strata immediately below the lowest stratum being mined. Acid-base accounting data must be presented on Module 7.1(B) "Geologic Log Drill Holes/ Overburden Analysis Data." Actual laboratory analysis sheets may be submitted in addition to Module 7.1(B). Forms of sulfur (when submitted) should be submitted on a separate sheet.
- 6) Techniques and methods of chemical analyses. References pertaining to technique or method should be cited as appropriate (e.g. Sobek, and others 1978, p. 47-50; ASTM Method D2492-84) and where a standard method is not used or has been modified, the method used should be described in detail.
- 7) An identification of any stratigraphic units possessing the potential for significant acid or alkaline production and an overall interpretation of the overburden analysis data. The criterion and rationale by which the overburden is being judged must be explained.
- 8) The name, address and telephone number of the individual(s) responsible for the collection and analysis of the data and interpretation of the data.

Although typically not required, an overburden analysis was conducted on the Freeport Sandstone from this proposed mine site in order to ascertain the chemical quality of the rock to be mined. An overburden analysis was performed on drill hole RS-3 from 0.0' to 74.60' and the results indicated the Freeport Sandstone to be predominantly neutral. Initial results from the overburden analysis were provided to the Department, and upon review, a corresponding request for additional overburden analysis testing was made. Additional testing was conducted on drillhole RS-2 to determine the consistency of the Freeport Sandstone throughout the proposed mine site. The overburden analysis testing was conducted from 44.9' to 53.9' in RS-2 and the results showed this material to be of similar quality to drillhole RS-3. It is believed the neutral nature of the Freeport Sandstone is consistent throughout the site. See the attached ABA spreadsheets for the lab testing results for these representative drillholes.


A review of the overburden results indicates there is no potentially acid producing overburden or material proposed to be mined. The siltstone below the Freeport Sandstone shows sulfur values ranging from 0.13 to 0.88 in RS-3 and 0.04 to 0.18 for RS-2. This material beneath the Freeport Sandstone will not be disturbed at the proposed mine site. As a best mining practice, 400 tons/acre of 100% CaCO3 material will be placed in the backfill to ensure a post-mining alkaline site. Note that this rate of application was determined based on the sulfur values for RS-3 to achieve a net NP greater than 12. See attached 7.5 Overburden Analysis, drill logs, cross-sections, and the Exhibit 6.2 map for reference.

#### 7.6 Special Considerations.

- a) Karst Geology. Operations sited within carbonate rock areas (e.g. limestone, dolostone) may be required to complete the Karst Permitting Supplement (5600-PM-BMP0456). [§ 77.404(5)]
  - N/A The site is not located within areas of known karst geology.
- b) Naturally Occurring Asbestos. Operations sited within areas that contain igneous and/or metamorphic rock types with the potential to host naturally occurring asbestos (NOA) may be required to complete the Naturally Occurring Asbestos (NOA) Application Supplement. (5600-PM-BMP0022). [§ 77.404(3)]
  - N/A There is no known naturally occurring asbestos within the sandstone proposed for mining.

If the applicant is unsure if special considerations apply to an operation, please contact the respective District Mining Office.


# Module 7: Geology Information Exhibit 7.1a) Geologic Column of the Freeport Formation



(Not to Scale)

Source: Geology and Mineral Resources of Somerset County, Pennsylvania, County Report 56A,1973, Plate 1, Generalized Stratigraphic Section of the Surface Rocks of Southern Somerset County

Module 7: Geology Information
Exhibit 7.2a) Geologic Map of The Southern Half of Somerset
County, Pennsylvania



(Not to Scale)

Source: Geology and Mineral Resources of Somerset County, Pennsylvania, County Report 56A,1973, Plate 1, Geologic Map of the Southern Half of Somerset County, Pennsylvania



Driller Rig type Drilling Method

H.S.A. Rock Core Type

Surface Elevation

Latitude Longitude Preferred Drilling

CME - 55, Track : Continuous Core

: 4 1/4" I.D.

: 2" 2031.4

: 39° 54' 35.4" : 79° 09' 11.9"

#### LOG OF BORING RS-1

(Page 1 of 1)

Date Drilled

: 06-14-2021 : 2177

ETI Project # Logged By:

: TM & AS

Reviewed By:

Ryan Stairs, P.G.

Depth in Feet	Surf. Elev. 2031.4	GRAPHIC	DESCRIPTION		RUN#	RUN DEPTH (FT')	RECOVERY %	RQD %	REMARKS
	2031.4		SOILS and unconsolidated material	5.5					
5-	2026.4		FREEPORT SANDSTONE, brownish-gray, weathered, broken t massive, brittle to hard, fine to coarse grain	$\overline{}$	2	<b>5.5-6.1</b> 6.1-11.1	100 52	<b>0</b> 8	Auger Refusal @ 5.5'
10-	2021.4		massive, brittle to hard, line to coarse grain		_				
15-	2016.4				3	11.1-16.1	100	60	
20-	2011.4				4	16.1-21.1	100	90	
25-	2006.4				5	21.1-26.1	90	56	
30-	2001.4		Sandy shale and siltstone zone at 30.4' to 34.1'		6	26.1-31.1	100	0	
	1996.4		Fine grain and massive sandstone at 34.1' to 46.8'		7	31.1-36.1	98	38	
					8	36.1-41.1	100	90	
40-	1991.4				9	41.1-46.1	100	92	
45-	1986.4		SANDY SHALE with CLAY, dark gray, very broken to broken,	46.8	10	46.1-51.1	56	10	
50-	1981,4		soft to semi-hard				57575		
55-	1976.4				11	51.1-56.1	82	0	
<u>설</u> 60-	1971.4				12	56.1-61.1	60	0	
ch Logs\RS-1.bor	1966.4	11.	END OF CORE	65.0	13	61.1-65.0	49	0	
	1961.4		END OF GOILE						
Scilling 75-	1956.4								
ne, LLC/									
ood Stor	1951.4								
J/Rockw	1946.4								
Wining 90 -	1941.4								
07-31-2024 Z:Wining\Rockwood Stone, LLC\Drilling\M-Te	1936.4								
100-	1								



Driller

Rig type Drilling Method

H.S.A.

Rock Core Type

Surface Elevation Latitude

Preferred Drilling

: CME - 55, Track Continuous Core

: 4 1/4" I.D.

: 2045.7 :39° 54' 27.9"

Longitude : 79° 09' 16.4"

#### **LOG OF BORING RS-2**

(Page 1 of 1)

Date Drilled

: 06-14 to 06-15-2021

ETI Project#

2177 TM & AS

Logged By: Reviewed By:

Ryan Stairs, P.G.

Depth in Feet	Surf. Elev. 2045.7	GRAPHIC	DESCRIPTION		RUN#	RUN DEPTH (FT')	RECOVERY %	RQD %	REMARKS
0-	2045.7								
	20,0		SOILS and unconsolidated material	4.0					
5-	2040.7		FREEPORT SANDSTONE with CLAY, brownish-gray,	-110	1	4.0-5.9	100	0	Auger Refusal @ 4.0'
10-	- 2035.7		weathered, broken to slightly broken, soft to semi-hard		2	5.9-10.9	100	30	
	- 2030.7				3	10.9-15.9	100	33	
	2025.7				4	15.9-20.9	100	35	
	- 2020.7				5	20.9-25.9	92	30	
	- 2015.7				6	25.9-30.9	96	54	
5.00	- 2010.7			2	7	30.9-35.9	80	40	
W. C. C. C.	- 2005.7				8	35.9-40.9	100	52	
5	- 2000.7				9	40.9-45.9	82	20	
5	- 1995.7			50.9	10	45.9-50.9	96	8	
1	- 1995.7		CLAYSTONE/SILTSTONE, dark dullish-gray, very broken to slightly broken, brittle to semi-hard	55.9	11	50.9-55.9	100	16	
	- 1985.7	222	END OF CORE						

07-31-2024 Z:\Mining\Rockwood Stone, LLC\Drilling\M-Tech Logs\RS-2 .bor 十 1985.7 65 - 1980.7 70 - 1975.7 75 - 1970.7 80 - 1965.7 85 - 1960.7 90 - 1955.7 7 1950.7

100



Driller

Rig type Drilling Method

H.S.A.

Rock Core Type Surface Elevation

Latitude Longitude : Preferred Drilling

: CME - 55, Track

: Continuous Core

: 4 1/4" I.D.

: 2"

: 2108.6 :39° 54' 18.2" : 79° 09' 01.4" LOG OF BORING RS-3

(Page 1 of 1)

Date Drilled

6-15-2021 : 2177

ETI Project #

: TM & AS

Logged By: Reviewed By:

Ryan Stairs, P.G.

Depth in Feet	Surf. Elev. 2108.6	GRAPHIC	DESCRIPTION	RUN#	RUN DEPTH (FT')	RECOVERY %	RQD %	REMARKS
0-	2108.6		SOILS and unconsolidated material					
5-	2103.6	Mr.	EDEEDODE CANDSTONE light brownigh grow weathered your	1	4.2-5.9	100	65	Auger Refusal @ 4.2'
	2098.6		FREEPORT SANDSTONE, light brownish-gray, weathered, very broken to slightly broken, soft to moderately hard	2	5.9-10.9	100	46	
	2093.6			3	10.9-15.9	100	30	
20-	2088.6			4	15.9-20.9	100	52	
25-	- 2083.6			5	20.9-25.9	100	80	
30-	2078.6		Fine grain and massive sandstone at 28.9' to 49.0'	6	25.9-30.9	100	48	
35-	2073.6			7	30.9-35.9	100	82	
40-	2068.6			8	35.9-40.9	100	100	
45-	- 2063.6			9	40.9-45.9	100	96	
50-	2058.6		Coarse grain/conglomerate sandstone at 49.0' to 54.2'	10	45.9-50.9	100	94	
55	- 2053.6			11	50.9-55.9	100	98	
60 – 65 –	2048.6			12	55.9-60.9	100	93	
	- 2043.6			13	60.9-65.9	100	100	
70-	2038.6	777	Coarse grain/conglomerate sandstone at 68.7' to 71.6' 71.6	14	65.9-70.9	100	100	
75	2033.6		SILTSTONE with sandy shale, dark gray, very broken to slightly broken, semi hard	15	70.9-75.9	100	72	
80	2028.6		END OF CORE	16	75.9-80.9	100	90	
85-	- 2023.6							
90-	2018.6							
	- 2013.6							
100-	i l							



07-31-2024 Z:Mining\Rockwood Stone, LLC\Drilling\M-Tech Logs\RS-4 bor

Driller

Rig type

Drilling Method

H.S.A.

Rock Core Type Surface Elevation

Latitude Longitude : Preferred Drilling

: CME - 55, Track

: Continuous Core

4 1/4" I.D.

: 2" : 2080.4

: 39° 54′ 23.4″ : 79° 09′ 03.5″ LOG OF BORING RS-4

(Page 1 of 1)

Date Drilled

: 06-16-2021 : 2177

ETI Project #

: TM & AS

Logged By: Reviewed By:

: Ryan Stairs, P.G.

Depth in Feet	Surf. Elev. 2080.4	GRAPHIC	DESCRIPTION	RUN#	RUN DEPTH (FT')	RECOVERY %	RQD %	REMARKS
0-	- 2080.4		SOILS and unconsolidated material					
5	- 2075.4	U.Srisa	3.9 FREEPORT SANDSTONE, light brownish-gray to light gray,	1	3.9-5.6	100	0	Auger Refusal @ 3.
10	- 2070.4		weathered, very broken to broken, soft to moderately hard	2	5.6-10.6	100	16	
3	- 2065.4			3	10.6-15.6	100	52	
3	- 2060.4		Shale zone from 17.5' to 19.5'	4	15.6-20.6	100	42	
4			Clay with claystone and siltstone zone at 23.5' to 28.2'	5	20.6-25.6	100	54	
3	2055.4		Fine to coarse grain sandstone at 28.2' to 52.6'	6	25.6-30.6	100	62	
3	- 2050.4			7	30.6-35.6	100	100	
3	2045.4			8	35.6-40.6	100	100	
10-	- 2040.4			9	40.6-45.6	100	100	
15	- 2035.4			10	45.6-50.6	100	92	
50 -	2030.4		Conglomerate sandstone at 52.6' to 67.4'	11	50.6-55.6	100	60	
55-	2025.4			12	55.6-60.6	100	98	
30 🖠	- 2020.4			13	60.6-65.6	100	88	
15	2015.4			14	65.6-70.6	100	100	
′o=	2010.4		73.8	-				
′5 +	2005.4		SHALE with CLAY/CLAYSTONE, dull gray, very broken to broken, brittle to semi hard 77.9	15	70.6-75.6	100	50	
30=	2000.4		SILTSTONE, dark gray, broken to slightly broken, semi-hard to hard 80.6/	16	75.6-80.6	100	50	
35	1995.4		END OF CORE					
00	1990.4							
95 <u></u>	1985.4							
00=								



Driller

Rig type

**Drilling Method** H.S.A.

Rock Core Type Surface Elevation

Latitude Longitude Preferred Drilling

: CME - 55, Track : Continuous Core

: 4 1/4" I.D.

: 2" : 2127.2 :39° 54' 10.6"

:79° 08' 58.4"

#### **LOG OF BORING RS-5**

(Page 1 of 1)

Date Drilled

: 06-17-2021 : 2177

ETI Project # Logged By:

TM & AS

Reviewed By:

Ryan Stairs, P.G.

	,							
Depth in Feet	Surf. Elev. 2127.2	GRAPHIC	DESCRIPTION	RUN#	RUN DEPTH (FT')	RECOVERY %	RQD %	REMARKS
0-	2127.2		SOILS and unconsolidated material					
_	3122.2		4.4		4.4-5.6	100	0	Auger Refusal @ 4.4'
	2122.2		FREEPORT SANDSTONE, brownish-gray, weathered, broken to slightly broken, brittle to hard, medium grain	2	5.6-10.6	100	20	
	2112.2		( )	3	10.6-15.6	<sub>2</sub> 100	48	
	2107.2			4	15.6-20.6	100	80	
	2102.2			5	20.6-25.6	100	52	
	2097.2		Conglomerate sandstone at 27.5' to 48.9'	6	25.6-30.6	100	59	
	2092.2			7	30.6-35.6	100	94	
	2087.2			8	35.6-40.6	100	100	
	2082.2			9	40.6-45.6	100	82	
	2077.2		Fine grain sandstone at 48.9' to 75.6'	10	45.6-50.6	100	98	
	2072.2			11	50.6-55.6	100	97	
	2067.2			12	55.6-60.6	100	94	
'RS-5	2062.2			13	60.6-65.6	100	100	
- 70 - A-Tech	2057.2			14	65.6-70.6	100	100	,
07-31-2024 Z:\Mining\Rockwood Stone, LLC\Drilling\M-Tech  2.22  2.24  2.25  2.26  2.26  2.26  2.26  2.26  2.26  2.27  2.26  2.27  2.	2052.2		75.6	15	70.6-75.6	100	100	
Stone, LL(	2047.2		SHALE with SILTSTONE and clay, dark gray, very broken to slightly broken, brittle to semi-hard	16	75.6-80.6	100	40	
s pood 85-	2042.2	777	84.2 CLAYSTONE, dull gray, brittle, very broken to broken 85.6	-1	80.6-85.6	100	40	
lining\Ro	2037.2		END OF CORE					
Z:\M								
31-2024	2032.2							
100-	1							



Driller

Rig type

**Drilling Method** 

H.S.A.

Rock Core Type Surface Elevation

Latitude Longitude : Preferred Drilling

CME - 55, Track

: Continuous Core

: 4 1/4" I.D.

: 2094.7 : 39° 54' 18.9"

: 2"

: 79° 09' 08.0"

#### LOG OF BORING RS-6

(Page 1 of 1)

Date Drilled

06-18 to 6-24-2021 : 2177

ETI Project #

TM & AS

Logged By: Reviewed By:

Ryan Stairs, P.G.

Depth in Feet Side Side Side Side Side Side Side Side	.   <del> </del>	DESCRIPTION	RUN#	RUN DEPTH (FT')	RECOVERY %	RQD %	REMARKS
0 - 2094	.7	SOILS and unconsolidated material 3.3					
5 2089	1.7	FREEPORT SANDSTONE, light brownish-gray, weathered, very	1	3.3-5.8	100	50	Auger Refusal @ 3.3
10 - 2084	.7	broken to broken, soft to moderately hard	2	5.8-10.8	100	8	
15 - 2079			3	10.8-15.8	76	0	
20 - 2074			4	15.8-20.8	90	66	
25 2069		Shale zone at 20.9' to 29.0'	5	20.8-25.8	100	32	
30 - 2064		Fine grain and massive sandstone at 29.0' to 80.7'	6	25.8-30.8	100	72	
35 - 2059			7	30,8-35.8	100	100	
40 - 2054			8	35.8-40.8	100	96	
45 - 2049			9	40.8-45.8	100	100	
50 - 2044			10	45.8-50.8	100	96	
55 - 2039			11	50.8-55.8	100	75	
60 - 2034			12	55.8-60.8	100	100	
65 - 2029			13	60.8-65.8	100	90	
70 2024			14	65.8-70.8	100	96	
75 - 2019			15	70.8-75.8	100	100	
80 - 2014		Conglements and coarse grain conditions at 90.71 to 92.91	16	75.8-80.8	100	100	
85 - 2009	77	Conglomerate and coarse grain sandstone at 80.7' to 82.8'  82.8  SILTSTONE with sandy shale, dark gray, very broken to slightly	17	80.8-85.8	100	88	
90 - 2004		broken, semi hard 90.8	18	85.8-90.8	100	52	
95 - 1999		END OF CORE				-	



Driller

Rig type

Drilling Method

H.S.A. Rock Core Type Surface Elevation

Latitude

: Preferred Drilling

: CME - 55, Track : Continuous Core

: 4 1/4" I.D.

; 2118.7 : 39° 54' 17.4"

: 2"

Longitude : 79° 08' 53.1"

#### LOG OF BORING RS-7

(Page 1 of 1)

Date Drilled

: 6-28-2021 : 2177

ETI Project # Logged By:

: TM & AS

Reviewed By:

: Ryan Stairs, P.G.

							1	i -
	Surf. Elev. 2118,7	GRAPHIC	DESCRIPTION	RUN#	RUN DEPTH (FT')	RECOVERY %	RQD %	REMARKS
0-	2118.7	65/74	SOILS and unconsolidated material 3.0				<u> </u>	
5-1	2113.7		FREEPORT SANDSTONE, light brownish-gray, weathered, very	1	3.0-5.8	100	39	Auger Refusal @ 3.0
10			broken to broken, soft to moderately hard	2	5.8-10.8	100	9	
15				3	10.8-15.8	100	70	
20				4	15.8-20.8	100	78	
25				5	20.8-25.8	100	68	
30			Fine grain and massive sandstone at 25.8' to 58.0'	6	25.8-30.8	100	80	
35				7	30.8-35.8	100	86	
40				8	35.8-40.8	100	100	
45				9	40.8-45.8	100	94	
50	2068.7			10	45.8-50.8	100	100	
55				11	50.8-55.8	100	99	
60			Conglomerate and coarse grain sandstone at 58.0' to 63.0'	12	55.8-60.8	100	86	
65	2053.7		63.0 SILTSTONE with sandy shale, dark gray, very broken to slightly	13	60.8-65.8	100	83	
70	2048.7		broken, semi hard 70.8	14	65.8-70.8	100	68	
3			END OF CORE					
75—	2043.7							
80 = 08	2038.7							
85 =	2033.7							
90=	2028.7							
95	2023.7							
100-								



Driller Rig type Drilling Method

H.S.A. Rock Core Type Surface Elevation

Latitude Longitude : Preferred Drilling

: CME - 55, Track : Continuous Core

: 4 1/4" I.D. : 2"

2058.8 39° 54' 27.4" 79° 09' 06.8" LOG OF BORING RS-8

(Page 1 of 1)

Date Drilled

: 06-28 to 06-29-2021

ETI Project #

TM & AS

Logged By: Reviewed By:

Ryan Stairs, P.G.

Depth in Feet	Surf. Elev. 2058.8	GRAPHIC	DESCRIPTION	RUN#	RUN DEPTH (FT')	RECOVERY %	RQD %	REMARKS
0-	- 2058.8	147/24	SOILS and unconsolidated material					
5	- 2053.8		8.3					Auger Refusal @ 8.3'
10-	- 2048.8		FREEPORT SANDSTONE, light brownish-gray to gray, weathered, very broken to slightly broken, brittle to hard, fine to	1	8.3-10.5	100	36	
15	- 2043.8		coarse grain	2	10.5-15.5	100	72	
20-	- 2038.8		Shale and Siltstone zone at 20.5' to 30.2'	3	15.5-20.5	100	62	
25	- 2033.8		Shall and Shalling 2016 at 20.0 to 30.2	4	20.5-25.5	100	6	
1	- 2028.8		Fine grain and massive sandstone at 30.2' to 44.4'	5	25.5-30.5	100	82	
1	- 2023.8			6	30.5-35.5	100	92	
3	- 2018.8			7	35.5-40.5	100	94	
=	~ 2013.8		Conglomerate and coarse grain sandstone at 44.4' to 50.0'	8	40.5-45.5	100	86	
	- 2008.8		50.0	9	45.5-50.5	100	86	
7	- 2003.8		SHALE/SILTSTONE, sandy, dark gray, broken to slightly broken, brittle to semi-hard	10	50.5-55.5	100	50	
1	- 1998.8			11	55.5-60.5	100	92	
3	- 1993.8		65.5	12	60.5-65.5	90	72	
3	1000.0		END OF CORE					VI
70	- 1988.8							
75	- 1983.8							

07-31-2024 Z:\Mining\Rockwood Stone, LLC\Drilling\M-Tech Logs\RS-8 .bor

80 - 1978.8

85 - 1973.8

90 - 1968.8

1963.8

95

100

# Rockwood Stone, LLC Rockwood Quarry

Black Township, Somerset County, PA

# **Module 7.5 Overburden Analysis**

Geochemical Testing Report for overburden analysis on drillhole RS-2 (8 pages)
Geochemical Testing Report for overburden analysis on drillhole RS-3 (29 pages)
Overburden Analysis Spreadsheet Calculation Summary for drillhole RS-3 (1 page)
Overburden Analysis Spreadsheet Calculation Summary and Mid-depth Acreage for RS-3 (1 page)
Overburden Analysis Spreadsheet for drillhole RS-3 (1 page)

# OVERBURDEN ANALYSIS SPREAD SHEET CALCULATION SUMMARY

OPERATOR: PERMIT NO:

COUNTY: Somerset TOWNSHIP: Black

COAL SEAMS: % SANDSTONE:

42

FIZZ

THRESHOLD VALUES

<u>₽</u> 8

SULFUR 0.5

DRILL HOLE: RS-3

OPERATION NAME: Rockwood Stone

ALK ADD (Va 100 %CaCO3)

BOTTOM ACREAGE 10.0

ACREAGE TOP

DEPTH TOTAL

74.6

10.0

MPA. NP or NNP/Thrs = Using Thresholds

	MI A, IN O MIN / IIIIS — OSING I II ESTIDIDS	3 - 031119 11116	SHOUSE				
	MPA/Thrs	MPA	NP/Thrs	ΑN	NNP/Thrs	NNP	Overburden
	(tons)	(tons)	(tons)	(tons)	(tons)	(tons)	(total tons)
TOTAL (TONS):	0	207	4,000	4,458	4,000	4,251	281,864
TOTAL (TONS/THOUSAND):	0.00	0.73	14.19	15.82	14.19	15.08	

0.73 15.82 15.08

Tons/1000 tons Tons/1000 tons

4,458 4,251 21.52

Tons/1000 tons

Without Thresholds @ 31.25

MPA (Total Tons) NP (Total Tons) Net Tons NP NP/MPA Ratio

With Thresholds @ 31.25

(1.1.0.) ONIO (1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	01.		
MPA (Total Tons)	0	Tons/1000 tons	0.00
NP (Total Tons)	4,000	Tons/1000 tons	14.19
Net Tons NP	4,000	Tons/1000 tons	14.19
NP/MPA Ratio	#DIV/0i		
Net NP Targets			
0	400	EXCESS	
0.5	386	3.5	301
1.0	372	4.0	287
1.5	358	4.5	273
2.0	344	5.0	259
2.5	330	5.5	245
3.0	315	0.9	231

44:///

228 200 171 143 115 87

9

369 341 312 284 256

7

**EXCESS** 


425 397

Net NP Targets

Without Thresholds @ 62.50	62.50		
MPA (Total Tons)	414	Tons/1000 tons	1.47
NP (Total Tons)	4,458	Tons/1000 tons	15.82
Net Tons NP	4,044	Tons/1000 tons	14.35
NP/MPA Ratio	10.76		
			Property and prope
Available NP			
(Tone per acre)	404	EXCESS	

	0		
With Thresholds @ 62.50	2.50		
MPA (Total Tons)	0	Tons/1000 tons	0.00
NP (Total Tons)	4,000	Tons/1000 tons	14.19
Net Tons NP	4,000	Tons/1000 tons	14.19
NP/MPA Ratio	#DIV/0i		
Available NP			
(Tons per acre)	400	EXCESS	

								N		0																							_			4	
							sp	OVRBRDN	(tons)	154,140	5,505	5,505	5,505	5.505	5.505	3,303	3,487	5,550	5,505	5,505	5,505	5,505	5,505	5,505	5,505	5,505	5,500	5,505	5,505	5,505	3,303	3,486	0	0	0	281,864	
							ig Threshol	NNP	(tons)	168	9	Ν.	- 0	, %	4	-	-	თ	0	2	90	Ţ	Ţ	0	4	4 ;	٩.	? ~	. m	-10	-7	-1	0	0	0	4,251	15.08
							/Thrs = Using Thresholds	NNP/Thrs	(tons)	0	0	0	0 0		0	0	0	0	0	0	0	0	0	0	0	0 (	0 0	o c	0	0	0	0	0	0	0	4,000	14.19
					200000000000000000000000000000000000000			ΔN	(tons)	216	80 (	n (	, n	- E	9	7	2	=	2	3	62	16	Ψ-	2	9	9 (	ກໍ້	23 2	26	10	<del>, -</del>	-	0	0	0	4,458	15.82
2580	1800	3670	3670	3670	3750	2000	3600	NP/Thrs	(tons)	0	0	0	0 0		0	0	0	0	0	0	0	0	0	0	0	0	0 0	0 0	0	0	0	0	0	0	0	4,000	14.19
8 -	8	E	ъ	8 5	চ	SO	2	MPA	(lons)	48	7	7	N 0	40	١٨	-	-	7	2	7	7	17	7	7	7	£ :	5 4	5 f2	17	21	7	12	0	0	0	207	0.73
CARBONOLITH	COAL	LIMESTONE	OTHER, SPOIL	SANDSTONE	SILTSTONE	SOIL	TILL	MPA/Thrs	(tons)	0	0	0	0 0	0 0	0	0	0	0	0	0	0	0	0	0	0	o (	<b>-</b>	<b>-</b>	. 0	0	0	0	0	0	0	0	0.00
000	8.2"			05-65	65	2108.6		FRACTION	SPOILED	1.00	0.05	0.05	000	50.00	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05	60,0	0.05	0.05	0.05	0.05	0.05	00.00	00.00	0.00		USAND):
(a CaCO3)			MS	STATE PLANE ZONE	T/WEST)	SURFACE ELEV. (feet	STATIC WATER (feet)	UNIT WT.	(t /acre-ft)	3670	3670	3670	3670	3670	3670	3670	3670	3700	3670	3670	3670	3670	3670	3670	3670	3670	3670	3670	3670	3670	3670	3670	3750	3750	3750	TONS):	TOTAL (TONS/THOUSAND):
AI K ADD (#a CaCO3)	LATITUDE	LONGITUDE	COAL SEAMS	STATE PLA	FEET (EAST/WEST)	SURFACE	STATIC W/	AREA	(acres)	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00	10,00	10.00	10.00	10,00	10.00	10.00	10.00	10.00	10.00	10,00	10.00	10.00	10.00	10.00	10.00	10.00	10,00	10.00	TOTAL (TONS):	TOTAL (
	. –	_						DEFICIT/	EXCESS	1,09	60	0,29	0.19	5.00	0.69	0,19	0.29	1.69	0.09	0.29	10.89	-0.23	-0.11	-0.01	0.79	-0.78	4.5	20 1	22	-1.85	-1.99	-3.04	3,50	6.74	5.74		
								dN	(t / 1000t)	1.40	140	0.60	0.50	5.40	1.00	0,50	09'0	2,00	0.40	0.60	11.20	2.90	0.20	0.30	1.10	1.10	0.50	4 10	4 70	1.90	0.20	0,40	31.00	10.80	9.80		
ÆET		Slone				CRES		FIZZ		0	0	0	0 0	0 0	0	0	0	0	0	0	0	0	0	0	0	0	۰,	- 0	0	-	0	0	-	0	0	l	
IS SPREADSHEET	TOWNSHIP: Black	OPERATION NAME: Rockwood Slone		1		MID DEPTH ACRES		COAL SULFUR	SEAM (percent)	0.01	0.01	0.01	0.01	0.0	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.10	0.01	0.01	0,01	90.0	0.11	0.09	0.00	0.12	0.07	0.11	0.88	0.13	0.13		
OVERBURDEN ANALYSIS	TOWN	RATION N	- 1	9 S		BOTTOM	10	ROCK	TYPE	5	SS	SS	SS	66 99	SS	35	SS	sh	88	88	\$2	SS	58	88	SS	88	SS	8 %	88	88	SS	SS	st	st	দ		
URDEN		OPE		SULFUR 0.5			10	THICK	(feet)	4.20	3.00	3.00	3,00	900	3.00	1.80	1.90	3.00	3.00	3,00	3,00	3,00	3,00	3.00	3.00	3.00	3.00	0.6	3.00	3.00	1,80	1.90	1.00	1.00	100		
OVERB		RS-3	it	VALUES			ACREAGE	BOTTOM	ELEV. (feet)	2104.40	2101.40	2098.40	2095,40	2082.40	2086.40	2084.60	2082.70	2079.70	2076.70	2073.70	2070.70	2067,70	2064,70	2061.70	2058,70	2055.70	2052.70	2049.70	2043.70	2040.70	2038,90	2037,00	2036.00	2035.00	2034.00		
OPERATOR	PERMIT NO:	DRILL HOLE:	3	THRESHOLD		TOTAL DEPTH	74.6	BOTTOM	DEPTH (feet)	4.20	7.20	10.20	13.20	19.20	22.20	24.00	25,90	28.90	31.90	34.90	37.90	40.90	43.90	46.90	49,90	52.90	05,55	56.30	64.90	67,90	02.69	71.60	72.60	73.60	74.60		





2005 N. Center Ave. Somerset, PA 15501

> 814/443-1671 814/445-6666 FAX: 814/445-6729

Thursday, August 8, 2024

Tom Matisko EARTHTECH INC 966 PLEASANT HILL ROAD SOMERSET, PA 15501

RE: Earthtech OB

Order No.: G2407F81

Dear Tom Matisko:

Geochemical Testing received 5 sample(s) on 7/26/2024 for the analyses presented in the following report.

There were no problems with sample receipt protocols and analyses met the TNI/NELAC, EPA, and laboratory specifications except where noted in the Case Narrative or Laboratory Results.

If you have any questions regarding these tests results, please feel free to call.

Sincerely,

Joelle Streczywilk

Environmental Laboratory Manager



#### **Geochemical Testing**

**EARTHTECH INC CLIENT:** 

Project: Earthtech OB

**CASE NARRATIVE** G2407F81 Lab Order:

No problems were encountered during analysis of this workorder, except if noted in this report.

**COC** Deficiencies

Other - See comments below

Comments: Correction tape/fluid used on COC.

COC Missing: Number of Containers

#### Glossary:

H - Method Hold Time exceeded and is not compliant with 40CFR136 Table II.

U - The analyte was not detected at or above the listed concentration, which is below the laboratory quantitation limit.

B - Analyte detected in the associated Method Blank

Q1 - See case narrative

ND - Not Detected

MCL - Contaminant Limit

J - Indicates an estimated value.

Q - Qualifier

QL -Quantitation Limit

DF - Dilution Factor

S - Surrogate Recovery outside accepted recovery limits

Date: 08-Aug-24

T - Sample received above required temperature and is not compliant with 40CFR136 Table II.

T1 - Sample received above required temperature

MDA - Minimum Detectable Activity.

\*\* - Value exceeds Action Limit

TICs - Tentatively Identified Compounds.

E - Value above quantitation range



#### Glossary (continued)

- Spike recovery limits are not applicable when the sample concentration exceeds the spike concentration by a factor of four or greater.
- B1 Dilution water blank exceeded method criterion.
- C1 CCV recovery above the acceptance limits. Results may be biased high.
- C2 CCV recovery below the acceptance limits. Results may be biased low.
- C3 ICV recovery above the acceptance limits. Results may be biased high.
- C4 ICV recovery below the acceptance limits. Results may be biased low.
- C5 Positive values verified by second column confirmation.
- C6 Confirmation analysis by another detector or chromatographic column was not performed.
- D1 The analysis did not meet the minimum DO depletion of at least 2 mg/L.
- D2 The analysis did not meet the minimum residual DO of at least 1 mg/L.
- D3 Sample required dilution due to a matrix interference.
- D4 Sample was diluted in the extraction steps due to marked matrix interferences.
- D5 Sample required dilution due to a chloride interference.
- D6 Sample was diluted and the reporting limits were raised to achieve method compliant internal standard recovery.
- D7 Sample was digested at a dilution due to the formation of a post-digestion precipitate.
- D8 Sample was digested at a dilution to achieve method compliant matrix spike recovery.
- D9 Sample was digested at a dilution to meet method compliant digestion criteria.
- E2 Unable to obtain a stable weight within specified limits due to sample matrix. Value is estimated.
- F1 Fecal sample tested positive for residual chlorine.
- H1 Due to under-depletion from the initial dilutions for BOD, the sample was reanalyzed outside the hold time.
- H2 Due to over-depletion from the initial dilutions for BOD, the sample was reanalyzed outside the hold time.
- H3 Sample was re-analyzed outside of hold time due to error during original analysis.
- H4 The Nitrite result used to report Nitrate was analyzed past the 48-hour holding time.
- Internal standard recovery above method acceptance limits. Results are estimated.
- Internal standard recovery was below method acceptance limits. Results are estimated.
- IP One of the instrument performance checks ( ) did not meet the acceptance criteria.
- L1 LCS above the acceptance limits. Result may be biased high.
- L2 LCS below the acceptance limits. Result may be biased low.
- L3 Analyte was spiked into the LCS, but was not recovered.
- M1 Matrix Spike recovery above the acceptance limits.
- M2 Matrix Spike recovery below the acceptance limits.
- M4 The matrix spike failed high for the surrogate.
- M5 The matrix spike failed low for the surrogate.
- M6 The reporting limits were raised due to sample matrix interference.

- M7 Recovery for matrix spike could not be quantified due to matrix interference.
- M8 Analyte was spiked into the MS, but was not recovered.
- M9 Analyte concentration was determined by the method of standard addition (MSA).
- N1 The lab does not hold accreditation from PA-DEP for this parameter by this method
- N2 PADEP does not accredit labs for this analyte by this method.
- N3 The lab is accredited for this method in West Virginia, but not in PA (its primary accrediting body).
- N4 PADEP does not accredit labs for this analyte by this method in drinking water.
- O1 The flashpoint tester cannot detect below 50 degrees F.
- O2 Result is temperature of the sample when flame observed. No flash observed. Result qualified.
- O3 The reporting limits were raised due to the high concentration of non-target compounds.
- O4 Sample was received with headspace.
- O5 Sample was received in incorrect container and is not compliant with 40CFR136 Table II.
- O6 Insufficient sample volume was received to comply with the method.
- P1 The pH of the sample was >2 and is not compliant with 40CFR136 Table II.
- P2 Sample contained residual chlorine and is not compliant with 40CFR136 Table II
- P3 The pH of the sample was <10 and is not compliant with 40CFR136 Table II.
- P4 Field preservation does not meet EPA or method recommendations for this analysis.
- P5 Acid preservation may not be appropriate for the analysis of 2-Chloroethylvinyl ether.
- P6 Sample required additional preservative upon receipt.
- P7 The sample was received unpreserved.
- P8 The pH of the sample was < 9 and is not compliant with 40 CFR136 Table II.
- R Relative Percent Difference (RPD) was above the control limit.
- R1 RPD above control limits between matrix spike and MS duplicates.
- R2 RPD above the control limit between duplicates.
- R3 RSD above the control limit between replicates.
- R4 RPD above control limits between Inorganic Carbon check and snike
- R5 RPD above control limits between control sample and control sample duplicates.
- S2 Surrogate recovery in the blank was below the control limit.
- S3 Surrogate recovery in the blank was above the control limit.
- S4 Surrogate recovery in the LCS is above the control limit.
- S5 Surrogate recovery in the LCS is below the control limit.
- SR Analyte recovery was outside the accepted recovery limits and above the control limit for RPD.
- T3 Target analyte found in trip/field blank.
- TC The MS tune check (tailing factor) did not meet the acceptance criteria.

# **Geochemical Testing**

Date: 08-Aug-24

CLIENT:

**EARTHTECH INC** 

Client Sample ID: RS-2, S-1, 44.9-47.9

Lab Order:

G2407F81

SOLID

**Project:** 

Earthtech OB

Lab ID: Matrix: G2407F81-001

Sampled By:

Earthtech, Inc.

**Collection Date:** 

7/26/2024 10:00:00 AM

**Received Date:** 

7/26/2024 1:57:00 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst: I	IRB				DEP OB MAN
Total Sulfur (p44)	0.01	0.01		%	1		08/07/24 12:00 A
Max Potential Acidity (Calc)	0.31	0.30		see note	1		08/07/24 12:00 A
Fizz Rating (p67)	0				1		08/07/24 12:00 A
Deficiency or Excess (Calc)	0.73			see note	1		08/07/24 12:00 A
Neutralization Potential (Tons) (p67)	1.0	0.1		see note	1		08/07/24 12:00 A

## **Geochemical Testing**

Date: 08-Aug-24

**CLIENT:** 

EARTHTECH INC

Client Sample ID: RS-2, S-2, 47.9-50.9

Lab Order:

G2407F81

Project:

Earthtech OB

Sampled By:

Earthtech, Inc.

Lab ID: Matrix: G2407F81-002

Collection Date:

7/26/2024 10:15:00 AM

SOLID

**Received Date:** 

7/26/2024 1:57:00 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst: I	RB				DEP OB MAN
Total Sulfur (p44)	0.01	0.01		%	1		08/07/24 12:00 AM
Max Potential Acidity (Calc)	0.31	0.30		see note	1		08/07/24 12:00 AM
Fizz Rating (p67)	0				1		08/07/24 12:00 AM
Deficiency or Excess (Calc)	1.48			see note	1		08/07/24 12:00 AM
Neutralization Potential (Tons) (p67)	1.8	0.1		see note	1		08/07/24 12:00 AM

NOTES:

# **Geochemical Testing**

Date: 08-Aug-24

**CLIENT:** 

EARTHTECH INC

Client Sample ID: RS-2, S-3, 50.9-51.9

Lab Order:

G2407F81

Project:

Earthtech OB

Lab ID:

G2407F81-003

Matrix:

**SOLID** 

Sampled By:

Earthtech, Inc.

Collection Date:

7/26/2024 10:30:00 AM

Received Date:

7/26/2024 1:57:00 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst: I	RB				DEP OB MAN
Total Sulfur (p44)	0.18	0.01		%	1		08/07/24 12:00 AM
Max Potential Acidity (Calc)	5.63	0.30		see note	1		08/07/24 12:00 AM
Fizz Rating (p67)	0				1		08/07/24 12:00 AM
Deficiency or Excess (Calc)	-4.59			see note	1		08/07/24 12:00 AM
Neutralization Potential (Tons) (p67)	1.0	0.1		see note	1		08/07/24 12:00 AM

NOTES:

## **Geochemical Testing**

Date: 08-Aug-24

**CLIENT:** 

EARTHTECH INC

**Client Sample ID:** RS-2, S-4, 51.9-52.9

Lab Order:

G2407F81

**SOLID** 

Project:

Earthtech OB

Lab ID: Matrix: G2407F81-004

Sampled By:

Earthtech, Inc.

Collection Date:

7/26/2024 10:45:00 AM

Received Date:

7/26/2024 1:57:00 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst: I	RB				DEP OB MAN
Total Sulfur (p44)	0.04	0.01		%	1		08/07/24 12:00 AM
Max Potential Acidity (Calc)	1.25	0.30		see note	1		08/07/24 12:00 AM
Fizz Rating (p67)	0				1		08/07/24 12:00 AM
Deficiency or Excess (Calc)	-0.31			see note	1		08/07/24 12:00 AM
Neutralization Potential (Tons) (p67)	0.9	0.1		see note	1		08/07/24 12:00 AM

NOTES:

## **Geochemical Testing**

Date: 08-Aug-24

**CLIENT:** 

EARTHTECH INC

Client Sample ID: RS-2, S-5, 52.9-53.9

Lab Order:

G2407F81

Project:

Earthtech OB

Lab ID: Matrix: G2407F81-005

SOLID

Sampled By:

Earthtech, Inc.

Collection Date:

7/26/2024 11:00:00 AM

Received Date:

7/26/2024 1:57:00 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst: I	RB				DEP OB MAN
Total Sulfur (p44)	0.04	0.01		%	1		08/07/24 12:00 AM
Max Potential Acidity (Calc)	1.25	0.30		see note	1		08/07/24 12:00 AM
Fizz Rating (p67)	0				1		08/07/24 12:00 AM
Deficiency or Excess (Calc)	-0.65			see note	1		08/07/24 12:00 AM
Neutralization Potential (Tons) (p67)	0.6	0.1		see note	1		08/07/24 12:00 AM

NOTES:



2005 N. Center Ave. Somerset, PA 15501

814/443-1671 814/445-6666 FAX: 814/445-6729

Monday, February 14, 2022

Heather Leydig EARTHTECH INC 966 PLEASANT HILL ROAD SOMERSET, PA 15501

Order No.: G2202449

Dear Heather Leydig:

Geochemical Testing received 27 sample(s) on 2/8/2022 for the analyses presented in the following report.

There were no problems with sample receipt protocols and analyses met the TNI/NELAC, EPA, and laboratory specifications except where noted in the Case Narrative or Laboratory Results.

If you have any questions regarding these tests results, please feel free to call.

Sincerely,

Timothy W. Bergstresser

Director of Technical Services

Timat W Buy trus

#### **Geochemical Testing**

CLIENT:

EARTHTECH INC

Project:

Lab Order:

G2202449

Date: 14-Feb-22

**CASE NARRATIVE** 

No problems were encountered during analysis of this workorder, except if noted in this report.

Core hole RS-3 was drilled on 6-15-21 and has been in storage in core boxes since. The client broke down the individual (27) samples on 2-7-22 for overburden analysis. Technically, the (OB) samples weren't obtained until 2-7-22.

Legend:

H - Method Hold Time exceeded and is not compliant with 40CFR136 Table II.

U - The analyte was not detected at or above the listed concentration, which is below the laboratory quantitation limit.

B - Analyte detected in the associated Method Blank

Q1 - See case narrative

ND - Not Detected

MCL - Contaminant Limit

J - Indicates an estimated value.

Q - Qualifier

QL -Quantitation Limit

DF - Dilution Factor

S - Surrogate Recovery outside accepted recovery limits

T - Sample received above required temperature and is not compliant with 40CFR136 Table II.

T1 - Sample received above required temperature

MDA - Minimum Detectable Activity.

\*\* - Value exceeds Action Limit

TICs - Tentatively Identified Compounds.

E - Value above quantitation range



## **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

**EARTHTECH INC** 

Client Sample ID: RS-3-1

Lab Order:

G2202449

4.2'-7.2'

Project:

Weathered Sandstone

Lab ID:

Sampled By:

Earthtech

G2202449-001

**Collection Date:** 

2/7/2022

Matrix:

SOLID

**Received Date:** 

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL				DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	1.4	0.1		%	1		02/11/22 7:30 AM

# **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

EARTHTECH INC

Client Sample ID: RS-3-2

Lab Order:

G2202449

7.2'-10.2'

Project:

Weathered Sandstone Earthtech

Lab ID:

G2202449-002

Sampled By: **Collection Date:** 

2/7/2022

Matrix:

SOLID

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL				DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	0.6	0.1		%	1		02/11/22 7:30 AM

## **Geochemical Testing**

Date: 14-Feb-22

CLIENT: EARTHTECH INC

Lab Order: G2202449

Project: Lab ID:

G2202449-003

Matrix: SOLID Client Sample ID: RS-3-3

10.2'-13.2' Weathered Sandstone

Sampled By:

Earthtech 2/7/2022

**Collection Date:** Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		DEP OB MAN P67					
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	0.5	0.1		%	1		02/11/22 7:30 AM

# **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

EARTHTECH INC

Client Sample ID: RS-3-4

Lab Order:

G2202449

13.2'-16.2' Weathered Sandstone

Project:

Lab ID:

Sampled By:

Earthtech

G2202449-004

**Collection Date:** 

2/7/2022

Matrix:

SOLID

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL				DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	8.0	0.1		%	1		02/11/22 7:30 AM

# **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

**EARTHTECH INC** 

Client Sample ID: RS-3-5

Lab Order:

G2202449

16.2'-19.2' Weathered Sandstone

Project:

Sampled By:

Earthtech

Lab ID:

G2202449-005

Collection Date:

2/7/2022

Matrix:

SOLID

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL		.,,		DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	5.4	0.1		%	1		02/11/22 7:30 AM

# **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

**EARTHTECH INC** 

Client Sample ID: RS-3-6

Lab Order:

G2202449

19.2'-22.2' Weathered Sandstone

Project:

Sampled By:

Earthtech

Lab ID:

G2202449-006

2/7/2022

Matrix:

SOLID

**Collection Date:** Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst: I	RLL				DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons)	1.0	0.1		%	1		02/11/22 7:30 AM

# **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

**EARTHTECH INC** 

Client Sample ID: RS-3-7

Lab Order:

G2202449

22.2'-24.0' Weathered Sandstone

Project:

Sampled By:

Earthtech

Lab ID:

G2202449-007

Collection Date:

2/7/2022

Matrix:

**SOLID** 

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL	31.31.11			DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	0.5	0.1		%	1		02/11/22 7:30 AM
units are: Tone CaCO3 / 1000 tone day							

## **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

EARTHTECH INC

Client Sample ID: RS-3-8

Lab Order:

G2202449

24.0'-25.9' Weathered Sandstone

Project:

Sampled By:

Lab ID:

G2202449-008

Earthtech 2/7/2022

Matrix:

**SOLID** 

**Collection Date:** Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL				DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	0.6	0.1		%	1		02/11/22 7:30 AM

### **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

EARTHTECH INC

Client Sample ID: RS-3-9

25.9'-28.9' Shale/Claystone

Lab Order:

G2202449

Sampled By:

Project:

G2202449-009

Collection Date:

Earthtech 2/7/2022

Lab ID: Matrix:

SOLID

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL				DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons)	2.0	0.1		%	1		02/11/22 7:30 AM

## **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

EARTHTECH INC

Client Sample ID: RS-3-10

Lab Order:

G2202449

28.9'-31.9' Sandstone

Sampled By:

Project:

Lab ID:

Earthtech

G2202449-010

Collection Date:

2/7/2022

Matrix:

**SOLID** 

Received Date:

2/8/2022 1:18:38 PM

						_, _,	.5011/1
Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL	711 - 1130			DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	0.4	0.1		%	1		02/11/22 7:30 AM

## **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

EARTHTECH INC

G2202449

Client Sample ID: RS-3-11

31.9'-34.9' Sandstone

Lab Order:

Project:

G2202449-011

Sampled By:

Earthtech

Lab ID:

Matrix:

**SOLID** 

**Collection Date: Received Date:** 

2/7/2022 2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst: I	RLL				DEP OB MAN P67
Total Sulfur	0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AN
Neutralization Potential (CaCO3 Tons)	0.6	0.1		%	1		02/11/22 7:30 AN

NOTES:

## **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

**EARTHTECH INC** 

Client Sample ID: RS-3-12

Lab Order:

G2202449

SOLID

Sampled By:

34.9'-37.9' Sandstone

Project:

Lab ID: Matrix:

G2202449-012

Earthtech

**Collection Date:** 

2/7/2022

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		DEP OB MAN P67					
Total Sulfur	0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	11,2	0.1		%	1		02/11/22 7:30 AM

### **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

**EARTHTECH INC** 

Client Sample ID: RS-3-13

Lab Order:

G2202449

37.9'-40.9' Sandstone

Project:

Lab ID:

Sampled By:

Earthtech 2/7/2022

Matrix:

G2202449-013

**SOLID** 

**Collection Date:** Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL				DEP OB MAN P67
Total Sulfur	0.10	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	2.9	0.1		%	1		02/11/22 7:30 AM

# **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

**EARTHTECH INC** 

Client Sample ID: RS-3-14

40.9'-43.9' Sandstone

Lab Order:

G2202449

Sampled By:

Project:

Lab ID:

Earthtech

Matrix:

G2202449-014 SOLID

**Collection Date:** 2/7/2022

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL				DEP OB MAN P67
Total Sulfur	0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	0.2	0.1		%	1		02/11/22 7:30 AM

## **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

**EARTHTECH INC** 

Lab Order:

G2202449

Project:

Lab ID:

G2202449-015

Matrix:

SOLID

Client Sample ID: RS-3-15

43.9'-46.9' Sandstone

Sampled By:

Earthtech

2/7/2022

Collection Date: Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL			,	DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	0.3	0.1		%	1		02/11/22 7:30 AM

### **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

EARTHTECH INC

Client Sample ID: RS-3-16

46.9'-49.9' Sandstone

Lab Order:

G2202449

Sampled By:

Project:

Lab ID:

G2202449-016

Earthtech 2/7/2022

Matrix:

SOLID

**Collection Date: Received Date:** 

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL				DEP OB MAN P67
Total Sulfur	< 0.01	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons)	1.1	0.1		%	1	16	02/11/22 7:30 AM

NOTES:

# **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

**EARTHTECH INC** 

Client Sample ID: RS-3-17

49.9'-52.9' Sandstone

Lab Order:

G2202449

Sampled By:

Earthtech

Project:

Lab ID:

G2202449-017

**Collection Date:** 

2/7/2022

Matrix:

SOLID

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL				DEP OB MAN P67
Total Sulfur	0.06	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	1.1	0.1		%	1		02/11/22 7:30 AM

### **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

EARTHTECH INC

Client Sample ID: RS-3-18

52.9'-55.9' Sandstone

Lab Order:

Project:

G2202449

Sampled By:

Earthtech

Lab ID:

G2202449-018

2/7/2022

Matrix:

**SOLID** 

**Collection Date: Received Date:** 

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL			·	DEP OB MAN P67
Total Sulfur	0.11	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	0.5	0.1		%	1		02/11/22 7:30 AM

## **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

**EARTHTECH INC** 

Client Sample ID: RS-3-19

Lab Order:

G2202449

**SOLID** 

55.9'-58.9' Sandstone

Project:

Sampled By:

Earthtech

Lab ID: Matrix: G2202449-019

**Collection Date:** 2/7/2022

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL				DEP OB MAN P67
Total Sulfur	0.09	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	1			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	2.2	0.1		%	1		02/11/22 7:30 AM

## **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

EARTHTECH INC

Client Sample ID: RS-3-20

Lab Order:

G2202449

Project:

58.9'-61.9' Sandstone

Sampled By:

Earthtech

Lab ID:

G2202449-020

**Collection Date:** 

2/7/2022

Matrix:

SOLID

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		DEP OB MAN P67					
Total Sulfur	0.09	0.01		%	1		02/11/22 7;30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons)	4.1	0.1		%	1		02/11/22 7:30 AM

## **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

**EARTHTECH INC** 

G2202449

Project:

Lab Order:

Lab ID:

G2202449-021

Matrix:

SOLID

Client Sample ID: RS-3-21

61.9'-64.9' Sandstone

Sampled By:

Earthtech

**Collection Date:** 

2/7/2022

**Received Date:** 

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	<b>s</b> ]	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst: I	RLL					DEP OB MAN P67
Total Sulfur	0.10	0.01		%		1		02/11/22 7:30 AM
Fizz Rating	0			%		1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	4.7	0.1		%		1		02/11/22 7:30 AM

# **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

**EARTHTECH INC** 

Client Sample ID: RS-3-22

Lab Order:

G2202449

64.9'-67.9' Sandstone

Project:

Sampled By:

Earthtech

Lab ID:

G2202449-022

**Collection Date:** 

2/7/2022

Matrix:

SOLID

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING			DEP OB MAN P67				
Total Sulfur	0.12	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	1			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons)	1.9	0.1		%	1		02/11/22 7:30 AM

### **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

**EARTHTECH INC** 

Lab Order: Project: Lab ID:

G2202449

G2202449-023

Matrix: SOLID Client Sample ID: RS-3-23

67.9'-69.7' Sandstone

Sampled By:

Earthtech

**Collection Date:** 

2/7/2022

**Received Date:** 

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		DEP OB MAN P67					
Total Sulfur	0.07	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	0.2	0.1		%	1		02/11/22 7:30 AM

# **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

**EARTHTECH INC** 

Client Sample ID: RS-3-24

69.7'-71.6' Sandstone

Lab Order:

G2202449

Sampled By:

Earthtech

Project: Lab ID:

G2202449-024

2/7/2022

Matrix:

SOLID

**Collection Date: Received Date:** 

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		DEP OB MAN P67					
Total Sulfur	0.11	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons)	0.4	0.1		%	1		02/11/22 7:30 AM

## **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** Lab Order: EARTHTECH INC

G2202449

G2202449-025

Lab ID: Matrix:

Project:

**SOLID** 

Client Sample ID: RS-3-25

71.6'-72.6' Siltstone

Sampled By:

Earthtech **Collection Date:** 2/7/2022

**Received Date:** 

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		DEP OB MAN P67					
Total Sulfur	0.88	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	1			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons)	31.0	0.1		%	1		02/11/22 7:30 AM

NOTES:

### **Geochemical Testing**

Date: 14-Feb-22

**CLIENT:** 

EARTHTECH INC

Client Sample ID: RS-3-26

72.6'-73.6' Siltstone

Lab Order:

G2202449

Sampled By:

Earthtech

**Project:** 

Lab ID:

G2202449-026

2/7/2022

Matrix:

**SOLID** 

**Collection Date: Received Date:** 

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		DEP OB MAN P67					
Total Sulfur	0.13	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons)	10.8	0.1		%	1		02/11/22 7:30 AM

## **Geochemical Testing**

Date: 14-Feb-22

CLIENT:

**EARTHTECH INC** 

Lab Order:

G2202449

Client Sample ID: RS-3-27

73.6'-74.6' Siltstone

Project:

Sampled By:

Earthtech

Lab ID:

G2202449-027

**Collection Date:** 

2/7/2022

Matrix:

SOLID

Received Date:

2/8/2022 1:18:38 PM

Analyses	Result	QL	Q	Units	DF	Date Prepared	Date Analyzed
ACID BASE ACCOUNTING		Analyst:	RLL			DEP OB MAN P67	
Total Sulfur	0.13	0.01		%	1		02/11/22 7:30 AM
Fizz Rating	0			%	1		02/11/22 7:30 AM
Neutralization Potential (CaCO3 Tons) NOTES:	9.8	0.1		%	1		02/11/22 7:30 AM