

Northwest Regional Office CLEAN WATER PROGRAM

Application Type
Wastewater Type
Facility Type
Sewage
SFTF

NPDES PERMIT FACT SHEET INDIVIDUAL SFTF/SRSTP

 Application No.
 PA0265152

 APS ID
 1069787

 Authorization ID
 1418924

Applicant Name	Char	otte Apartments, LLC	Facility Name	Dollar General 17942 Ellwood Road	
Applicant Address 10		Archibald Street	Facility Address	4029 Ellwood Road	
	Kans	as City, MO 64111-2214		New Castle, PA 16101-6407	
Applicant Contact	Robe	rt Ellis	Facility Contact		
Applicant Phone	psmit	h@hotmail.com	Facility Phone		
Client ID	3719	76	Site ID	819291	
SIC Code	5399		Municipality	Slippery Rock Township	
SIC Description	Retail Trade - Miscellaneous General Merchandise Stores		_ County	Lawrence	
Date Application Received		November 7, 2022	WQM Required	Yes - Transfer	
Date Application Accepted		November 10, 2022	WQM App. No.	_ 3717401 T-1	

Summary of Review

This SFTF serves a retail store. As part of this NPDES Permit renewal, the permit is transferring ownership from New Castle DDP, LLC to Charlotte Apartments, LLC.

Treatment consists of a 1000 gallon 2-compartment septic tank with effluent filter, Orenco AdvanTex AX20-RTUV wastewater system with UV disinfection, and discharge pump tank. System design is 0.0004 MGD with expected annual average flows of 0.0002 MGD.

The facility is signed up for and using the eDMR system for reporting of effluent sampling results.

Sludge use and disposal description and location(s): Septage must be pumped and hauled off-site by a septage hauler for land application under a general permit authorized by PADEP or disposal at an STP.

Public Participation

DEP will publish notice of the receipt of the NPDES permit application and a tentative decision to issue the individual NPDES permit in the *Pennsylvania Bulletin* in accordance with 25 Pa. Code § 92a.82. Upon publication in the *Pennsylvania Bulletin*, DEP will accept written comments from interested persons for a 30-day period (which may be extended for one additional 15-day period at DEP's discretion), which will be considered in making a final decision on the application. Any person may request or petition for a public hearing with respect to the application. A public hearing may be held if DEP determines that there is significant public interest in holding a hearing. If a hearing is held, notice of the hearing will be published in the *Pennsylvania Bulletin* at least 30 days prior to the hearing and in at least one newspaper of general circulation within the geographical area of the discharge.

Approve	Deny	Signatures	Date
X		Adam J. Pesek Adam J. Pesek, E.I.T. / Project Manager	March 14, 2023
Х		Chad W. Yurisic, P.E. / Environmental Engineer Manager	3/23/2023

ischarge, Receiving Wa	aters and Water Supply Info	rmation				
	astle South	Design Flow (MGD) Longitude Quad Code	0.0004 -80° 15' 44" 1103			
Wastewater Description	n: Sewage Effluent					
	kunk Run 26221272	Stream Code	34025 2.46			
Drainage Area 0.	16	Yield (cfs/mi²)	0.0517			
Q ₇₋₁₀ Flow (cfs) 0.	00827 245	Q ₇₋₁₀ Basis Slope (ft/ft)	USGS #03109300 CWF			
· · · · · · · · · · · · · · · · · · ·)-C	Chapter 93 Class.				
Existing Use		Existing Use Qualifier				
Exceptions to Use		Exceptions to Criteria				
Assessment Status	Attaining Use(s)					
Cause(s) of Impairment	<u> </u>					
Source(s) of Impairmen	t					
TMDL Status	TMDL Status		Name			
Background/Ambient Data		Data Source				
pH (SU) <u>7.0</u>		Default				
Temperature (°C) 20		Default (CWF)				
Hardness (mg/L) Other:						
Nearest Downstream P	ublic Water Supply Intake	PA American Water Company	/ – Ellwood District			
PWS Waters Con	noquenessing Creek	Flow at Intake (cfs)	67			
PWS RMI 0.2		Distance from Outfall (mi)	12.06			

Changes Since Last Permit Issuance: PWS Intake on Slippery Rock Creek was decommissioned.

Other Comments:

Compliance History				
Summary of DMRs:	Monthly eDMRs have been submitted since the SFTF became operational. A review of eDMRs show numerous violations of fecal coliform, BOD ₅ , and TSS. Based on this observation, the system does not appear to be able to treat at a consistent tertiary level that the STP was designed for.			
Summary of Inspections:	12/1/2022 NOV to current owners for failure to pay annual fee. Site was last inspected on 6/5/2019 with no violations noted on the inspection report.			

Other Comments: There are currently no open violations listed in EFACTS for this permittee (3/14/2023). 3/23/2023 CWY

Proposed Effluent Limitations and Monitoring Requirements

The limitations and monitoring requirements specified below are proposed for the draft permit, and reflect the most stringent limitations amongst technology, water quality and BPJ. Instantaneous Maximum (IMAX) limits are determined using multipliers of 2 (conventional pollutants) or 2.5 (toxic pollutants). Sample frequencies and types are derived from the "NPDES Permit Writer's Manual" (362-0400-001), SOPs and/or BPJ.

Outfall 001, Effective Period: Permit Effective Date through Permit Expiration Date.

	Effluent Limitations					Monitoring Requirements		
Parameter	Mass Units (lbs/day) (1)		Concentrations (mg/L)				Minimum ⁽²⁾	Required
Farameter	Average Monthly	Average Weekly	Minimum	Average Monthly	Maximum	Instant. Maximum	Measurement Frequency	Sample Type
Flow (GPD)	Report	XXX	XXX	XXX	XXX	XXX	1/month	Estimate
pH (S.U.)	XXX	XXX	6.0 Inst Min	XXX	XXX	9.0	Upon Request	Grab
BOD5	XXX	XXX	XXX	10.0	XXX	20	1/month	Grab
TSS	XXX	XXX	XXX	10.0	XXX	20	1/month	Grab
Fecal Coliform (No./100 ml)	XXX	XXX	XXX	200 Geo Mean	XXX	1000	1/month	Grab

Compliance Sampling Location: Outfall 001 (after disinfection).

Other Comments: