2700-FM-BAQ0023 2/2015 pennsylvania pepartment of environmental protection		INSPECTIO	N REPORT		Commonwealth of Pennsylvania Department of Environmental Protec Air Quality Program		ronmental Protection y Program	
Date(s) of Inspection: TV ☐ PA ☐ GP 🖫	4	Permit #(s): +9-04-0080	Expiration	_ )	Case	· #:	PFID#:	
				17/22	-		823349	
				ockhill Two		Bucks		
Plant Name: Physical Location:				Colour 100/2		eral ID — Plant Code	#:	
East Rockhill Jamy Same as below  Responsible Official: Mailing Address:								
Jim Allen			2105 N. ROUKHII RE					
From #(s): 409 - 743 - 0350			Sellersville, PA 18960					
409 - 743 -0350								
Mark (X) All Inspection Types That Apply To This Inspection:								
Full Compliance Evaluation (FCE)		Plan Approval Inspection				File Review (FR)		
Operating Permit Inspection (PI)		Initial Permit Inspection (IPI)				Complaint Inspection (CI)		
Routine/Partial (RTPT)		Follow-Up Inspection (Ref. Date:)				Sample Collection	n (SC)	
Minor Source(s) Inspection (RFD)		Stack Test Observation				Multi-Media Inspection (MM)		
Other: MA Test Obsavation   Announced								
Annual Compliance Certification Received: YES NO X N/A				Date Received:				
AIMS Report Received: YES NO N/A				Date Received:				
Mark (X) All Activities That Apply:								
File Review	又	Pre-Inspection Briefing				Exit Interview/Briefing		
Pre-Inspection Observations	刄	Check For New/Unreported Sources				Sample(s) Collected		
☐ Visible Emissions Observations		Verify Operation of CEMS			Other			
Comments/Recommendations: Enforcement since last FCE \( \text{Yes}\) No (If yes, attach summary) \[ \left\) Wrived on Site at 9:00 am to conduct a Method 9 visible \[ \text{emissions}\) observation. \( \text{Method}\) Tim Allen From R.E. Pierson								
and Ronald Bennett From Compliance Plus Services, the First								
test began at 9:40 am and the second test began at								
11:10 am. six Efferent points within the Melott Screening								
operation were observed and no dust was noted the								
crushers were not in operation. I observed that no turther								
construction of the primary/permanent cousties has taken place,								
when i appeared in the appear is the second of the second								
and limited no highlive emissions or mulchors.								
Compliance Status:   In   Out   Pending   Awaiting Co. Report  Needs a Follow-Up Inspection?   Yes   No								
Company Representative:	Title			Signature:		<u> </u>	Date:	
James O. Allen	١ وز	Site Sunt		MAL		In.	10/31/18	
DEP Representative:	Title	÷ , , , ,		Signature:			Date/Time:	
Jennifer Ramos-Bushingen AC Specialist Junio Panno-Bushingen 12/615							wym 12huspin	
This document is official notification that a representative of the Department of Environmental Protection, Air Quality Program, inspected the identified site. The findings of this inspection are shown above and on any attached pages, and may include violations uncovered during the inspection. Violations may also be discovered upon review of sample results or from any additional review of Department records. Notification will be forthcoming, if such violations are noted.								
Page of eFacts Inspection ID#: 2796932 Date: 10/31/18 Reviewed By Say								
☐ White – Regional Office ☐ Yellow – Site ☐ Pink – District Office								