

NARRATIVE REPORT FORM

Facility Name: Glenwood Drive & Walker Road

Primary Facility ID: 881609

| | | | |
|---|--|---|---|
| Inspection Date: 9/19/25 | | Inspection Time: 10:00- 11:30 | Lat/Long: |
| Program: | <input type="checkbox"/> Storage Tanks | <input type="checkbox"/> HSCA | <input checked="" type="checkbox"/> LRP |
| Owner Name: | | Inspection ID: | Site ID: |
| Facility Location (911) Address: [REDACTED] Washington Crossing, PA 18977 | | Municipality: Upper Makefield Township County: Bucks County | |
| Responsible Official Name: Bradford Fish Title: Senior Environmental Specialist Emergency Response & Remediation | | Responsible Official Address: 100 Green Street Marcus Hook, PA 19061 | |
| Responsible Official Telephone: 610.859.6297 Email Address: Bradford.fish@energytransfer.com | | Interviewee Name: Affiliation: Email Address: | |
| Narrative: <p>The purpose of today's site visit was to observe installation of the supply well at [REDACTED] Entities present at the site include Olivia Budnovitch (DEP), Stantec, Moody and Associates, Inc, Raab Drilling, and Rettew. Stantec was performing air monitoring and David Anderson (DA) from Moody was the Geologist overseeing drilling activities.</p> <p>I arrived onsite at 10:00 and drilling started shortly after my arrival (Photo #1). Sound barriers were placed against the residence on the property and along Glenwood Drive (Photo #2 & #3). There were multiple Summa Cannisters placed around the property for air monitoring (Photo #4).</p> <p>DA informed me that there would be no advancement in depth today. They were in the process of reaming out the previously drilled 6-inch hole into an 8-inch hole from 80 feet below ground surface (bgs) to 150 feet bgs. These activities were completed at 11:00. After drilling was complete, the activities for the day were to set the casing from 80-150 feet bgs and set the grout to dry over the weekend.</p> <p>I noted there was a Groundwater and Environmental Services (GES) crew performing routine total fluids recovery on the recovery well network on Glenwood Drive.</p> <p>I departed from the neighborhood at 11:30.</p> | | | |

| | | | |
|-------------------------|--|--------------|-------------------------|
| DEP Representative Name | DEP Representative Signature | Title | Date: 9/22/25 |
| Olivia Budnovitch |  Olivia Budnovitch <small>Date: 2025.09.22 09:28:37 -04'00'</small> | Geoscientist | Telephone: 484.250.5705 |

Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.


| | | | |
|------------------|-----------------------|-------|------------|
| Interviewee Name | Interviewee Signature | Title | Date: |
| | | | Telephone: |


Facility Name: Glenwood Drive & walker Road

Primary Facility ID: 881609

MAPS / PHOTOGRAPHS / ATTACHMENTS

Map #1: Google Earth location of Washington Crossing neighborhood



| | | | |
|---|--|--|--|
| <p>Map #1: Google Earth location of Washington Crossing neighborhood</p>  | | | |
|---|--|--|--|

| | | | | |
|--|---|--|-----------------------|-------------------------|
| DEP Representative Name Olivia Budnovitch | DEP Representative Signature Olivia Budnovitch | Digital signature of Olivia Budnovitch Digitally signed by Olivia Budnovitch Date: 2025.09.22 09:29:48 -04'00' | Title Geoscientist | Date: 9/22/25 |
| | | | | Telephone: 484.250.5705 |

Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

| | | | |
|------------------|-----------------------|-------|------------|
| Interviewee Name | Interviewee Signature | Title | Date: |
| | | | Telephone: |

NARRATIVE REPORT FORM

Facility Name: Glenwood Drive & Walker Road

Primary Facility ID: 881609

| | |
|--|---|
| <p>Photo #1: Drill Rig set up for [REDACTED] supply well installation</p>  | <p>Photo #2: Sound barrier set up along Glenwood Dr</p>  |
| <p>Photo #3: Sound barrier set up along [REDACTED] residence</p>  | <p>Photo #4: Air monitoring device</p>  |

| | | | |
|--|---|------------------------------|--|
| DEP Representative Name Olivia Budnovitch | DEP Representative Signature  Olivia Budnovitch <small>Date: 2025.09.22 09:30:44 -04'00'</small> | Title Geoscientist | Date: 9/22/25 Telephone: 484.250.5705 |
| <i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.</i> | | | |
| Interviewee Name | Interviewee Signature | Title | Date: Telephone: |