



COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF MINING PROGRAMS

INSPECTION REPORT  
NONCOAL

Date: 4/15/2016

Mine Name New Hope Quarry

Weather Clear 55 F

Complete  Partial

On Site Times 1045 - 1500

PERMITTEE New Hope Crushed Stone & Lime Co.	TOWNSHIP Solebury	COUNTY Bucks	PERMIT NO. 7974SM3
ADDRESS: PO Box 248 New Hope PA 18938-0248	VIOLATION HISTORY 0 NOV'S 1 CO'S	<input type="checkbox"/> VIOLATIONS NOTED PREVIOUS VIOLATIONS: <input checked="" type="checkbox"/> CORRECTED <input type="checkbox"/> UNCORRECTED	<input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER
GENERAL MINING INFORMATION: Large <input checked="" type="checkbox"/> Small 10,000 <input type="checkbox"/> 2,000 <input type="checkbox"/> GP 105 <input type="checkbox"/> GP 103 <input type="checkbox"/> Expiration Date:			LICENSE NO. & EXP. DATE 1879 8/31/2016 OPERATIONAL STATUS Active

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Limestone open pit- ~2550' x ~1100' x ~315'  
 b. Equipment-Use & Conditions: crushing/screening plants; FELs; haul trucks; track excavators; backhoe; water truck- good condition  
 c. Contract Miner: Yes  No  Name: \_\_\_\_\_ d. Approved Blast Plan: Yes  No  Is there blasting today? Yes  No

Approved Acres	Approved Pit Volume	Progress of Reclamation	Liability
Mining Area: 141 Support:	yd <sup>3</sup>	Regraded acres Topsoiled acres	Current Bond
Disturbed not planted:	Current Pit Volume	Water Impoundment : Acres Approved Acres Actual	\$465,850
Affected acres	yd <sup>3</sup>	Planted, Grasses acres	Current Liability
Mining Area: 141 Support:	Selective Grading of Highwall	Trees Required ac. Planted ac.	\$
Disturbed not planted:	Approved: yd <sup>3</sup> Current:	Meeting Stage 1 criteria: acres	
Highwall Bond (Blasting to achieve reclamation) Approved/Affected			
<20 ft.:	ft. ft.	>20<30 ft. ft. ft.	>30<40 ft. ft. ft.
		>40<50 ft. ft. ft.	>50 ft. ft. ft.

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	Unauthorized Mining		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Air Resources Protection		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Mining License		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Concurrent Reclamation		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Signs and Markers		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Backfilling and Grading		<input type="checkbox"/>	
<input type="checkbox"/>	Topsoil-Rem/Storage/Handling		<input type="checkbox"/>		<input type="checkbox"/>	Revegetation		<input type="checkbox"/>	
<input type="checkbox"/>	Effluent Standard		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Haul Roads		<input type="checkbox"/>	
<input type="checkbox"/>	Diversions and Conveyance		<input type="checkbox"/>		<input checked="" type="checkbox"/>	General Safety		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Sediment Control Measures		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Permit Conditions		<input type="checkbox"/>	
<input type="checkbox"/>	Treatment Facilities		<input type="checkbox"/>		<input type="checkbox"/>	Temporary Mining Cessation		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Sedimentation Ponds		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Distance Limitations-Barriers		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Discharge Structures		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Bench Development		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Dams, Ponds-Design/Const./Maint.		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Permit Line Setback		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Water Monitoring-Ground/Surface		<input type="checkbox"/>		<input type="checkbox"/>	Stability Analysis		<input type="checkbox"/>	
<input type="checkbox"/>	Water Discharge-Underground Mine		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Blasting Requirement		<input type="checkbox"/>	

COMMENTS AND RECOMMENDATIONS: This partial inspection was conducted in the company of Mr. Jeff Phillips (Superintendent) and Mr. Tim Romano (Foreman). The floating pump was on the pontoon and being attached to the piping. The pump was running by 3 PM. Material was placed on some benches to be pushed for reclamation. Some large trees were removed in the areas to be reclaimed first. The operator was reminded that reclamation work needed to continue as noted in items 2 and 3 in the Department letter dated January 29, 2016. Failure to comply with the terms and conditions of the January 29, 2016 letter will result in enforcement action.

Current depth: -120 MSL Approved to: -120 MSL

Violation History: CO issued 10/1/2015 - Section 7 (c)(5) and (10) of the Noncoal Surface Mining Conservation and Reclamation Act, 52 P.S. § 3307(c)(5) and (10). (GL)

Person Contacted Mr. Tim Romano	Title Foreman	Discharge/Seeps: <input checked="" type="checkbox"/> yes <input type="checkbox"/> no Range of Samples Collected	Samples Collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no to
Signature	Investigator Signature Amiee Bollinger	Collector ID No. 4519	Employee ID No. 608058

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

White - District File

Yellow - Permittee

Pink - Inspector