


NHCS 2023

2023 Google Earth Image and Showing Locations of Test Pits, Prior Location of Primrose Creek, 2023 Found Culvert and Proposed Creek Restoration Path

Appendix 1, Exhibit 1, Plate 8

Legend

- Approx. Path of Creek Restoration
- Downstream Primrose Creek
- Found (2023) Culvert Location
- Highwall Failure Area
- Prior Path Primrose Creek



Google Earth

Image © 2023 Airbus

200 ft