



COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF MINING PROGRAMS

INSPECTION REPORT  
NONCOAL

Date: 4/18/2017

Mine Name New Hope Quarry  
Weather Clear 56 F

Complete  Partial  On Site Times 1018 - 1121

PERMITTEE New Hope Crushed Stone & Lime Co.	TOWNSHIP Solebury	COUNTY Bucks	PERMIT NO. 7974SM3
ADDRESS: PO Box 248 New Hope PA. 18938-0248	VIOLATION HISTORY 0 NOV'S 2 CO'S	<input type="checkbox"/> VIOLATIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: <input type="checkbox"/> CORRECTED <input type="checkbox"/> UNCORRECTED	<input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER
GENERAL MINING INFORMATION: Large <input checked="" type="checkbox"/> Small 10,000 <input type="checkbox"/> 2,000 <input type="checkbox"/> GP 105 <input checked="" type="checkbox"/> GP 103 <input type="checkbox"/> Expiration Date: 8/10/2021			LICENSE NO. & EXP. DATE 1879 8/31/2017 OPERATIONAL STATUS Active

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Limestone open pit - ~2550' x ~1100' x ~315'  
b. Equipment-Use & Conditions: crushing/screening plants; FELs; haul trucks; track excavators; backhoe; water truck- good condition  
c. Contract Miner: Yes  No  Name: \_\_\_\_\_ d. Approved Blast Plan: Yes  No  Is there blasting today? Yes  No

Approved Acres	Approved Pit Volume	Progress of Reclamation		Liability
Mining Area: 141 Support:	yd <sup>3</sup>	Regraded acres	Topsoiled acres	Current Bond
Disturbed not planted:	Current Pit Volume yd <sup>3</sup>	Water Impoundment: Acres Approved		\$356,199.73 (paid in)
Affected acres		Acres Actual		
Mining Area: 141 Support:	Selective Grading of Highwall	Planted, Grasses	acres	Current Liability
Disturbed not planted:	Approved: yd <sup>3</sup> Current:	Trees Required	ac. Planted	\$1,144,028.80
		Meeting Stage 1 criteria: acres		

Highwall Bond (Blasting to achieve reclamation) Approved/Affected

<20 ft.:	ft.	ft.	>20<30 ft.	ft.	ft.	>30<40 ft.	ft.	ft.	>40<50 ft.	ft.	ft.	>50 ft.	ft.	ft.
----------	-----	-----	------------	-----	-----	------------	-----	-----	------------	-----	-----	---------	-----	-----

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	Unauthorized Mining		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Air Resources Protection		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Mining License		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Concurrent Reclamation		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Signs and Markers		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Backfilling and Grading		<input type="checkbox"/>	
<input type="checkbox"/>	Topsoil-Rem/Storage/Handling		<input type="checkbox"/>		<input type="checkbox"/>	Revegetation		<input type="checkbox"/>	
<input type="checkbox"/>	Effluent Standard		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Haul Roads		<input type="checkbox"/>	
<input type="checkbox"/>	Diversions and Conveyance		<input type="checkbox"/>		<input checked="" type="checkbox"/>	General Safety		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Sediment Control Measures		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Permit Conditions		<input type="checkbox"/>	
<input type="checkbox"/>	Treatment Facilities		<input type="checkbox"/>		<input type="checkbox"/>	Temporary Mining Cessation		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Sedimentation Ponds		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Distance Limitations-Barriers		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Discharge Structures		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Bench Development		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Dams, Ponds-Design/Const./Maint.		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Permit Line Setback		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Water Monitoring-Ground/Surface		<input type="checkbox"/>		<input type="checkbox"/>	Stability Analysis		<input type="checkbox"/>	
<input type="checkbox"/>	Water Discharge-Underground Mine		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Blasting Requirement		<input type="checkbox"/>	

COMMENTS AND RECOMMENDATIONS: This partial inspection was conducted in the company of Mr. Tim Romano (Co-Superintendent). One front-end loader, two haul trucks and one dozer we working on reclamation in the SE corner top level. Pumping volumes were about 500,000 GPD. Water level in the pit is about -80 MSL. One front-end loader was working in the stock area. One front-end loader and two haul trucks were removing shot rock from the 4<sup>th</sup> level. The water truck was wetting the haul roads. Mr. Romano and I discussed increasing the catch berm height and installing check dams along the pit haul road once material is pushed into the pit. We also reviewed the location of the proposed haul road on the N side of the permit. All MSHA citations were terminated. The operator is reminded to submit the monthly truck count and estimated volume of material used for reclamation by the 5th of each month. The operator was reminded to have the reclamation hours and volumes in the quarterly report. The operator was reminded that reclamation work needed to continue as noted in items 2 and 3 in the Department letter dated January 29, 2016. Failure to comply with the terms and conditions of the January 29, 2016 letter will result in enforcement action.

Violation History: CO issued 8/26/2016- Subchapter E 77.102(f)(1) & (2) and Section 11(b) of the Noncoal Surface Mining Conservation and Reclamation Act. (GL)

CO issued 10/1/2015 - Section 7 (c)(5) and (10) of the Noncoal Surface Mining Conservation and Reclamation Act, 52 P.S. § 3307(c)(5) and (10). (GL)

Person Contacted Mr. Tim Romano	Title Co-Superintendent	Discharge/Seeps: <input checked="" type="checkbox"/> yes <input type="checkbox"/> no	Samples Collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature	Investigator Signature Amiee Bollinger	Range of Samples Collected	Collector ID No. 4519 Employee ID No. 608058

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

White - District File

Yellow - Permittee

Pink - Inspector

## **APPEAL NOTICE**

Any person aggrieved by this action may appeal, pursuant to Section 4 of the Environmental Hearing Board Act, 35 P.S. Section 7514, and the Administrative Agency Law, 2 Pa. C.S. Chapter 5A, to the Environmental Hearing Board, Second Floor, Rachel Carson State Office Building, 400 Market Street, P.O. Box 8457, Harrisburg, PA 17105-8457, 717-787-3483. TDD users may contact the Board through the Pennsylvania Relay Service, 800-654-5984. Appeals must be filed with the Environmental Hearing Board within 30 days of receipt of written notice of this action unless the appropriate statute provides a different time period. Copies of the appeal may be obtained from the Board. At 717-787-3483. This paragraph does not, in and of itself, create any right of appeal beyond that permitted by applicable statutes and decisional law.

Violations of performance standards on operations permitted prior to the effective date of the regulations promulgated pursuant to Act 219, the 1984 Noncoal SMCRA shall be cited as a violation of permit conditions and shall be designated as PC on the reverse side in the column headed by PC or Reg.

Violations of performance standards on operations permitted after the effective date of the regulations promulgated pursuant to Act 219, the 1984 Noncoal SMCRA shall be cited as a violation of the regulations.