

10:	T. Boratski
-	Page 1 of1
	A. bolling

Mine	Name	New Hope	Onarry
1611116	HOLLIC	TACAL TIODO	√ mm i √ m m m m m m m m m m m m m

INSPECTION REPORT

NONCOAL On Site Times													
Weat	her				Comple	ete	Partial	Χ.					
PERMITTEE			TOWNSHIP				COUNTY			PERMIT NO.			
New Hope Crushed Stone & Lime Co.			Solebury				Bucks			7974SM3			
ADDRESS			VIOLATION VIOLATIC			IONS NO	ONS NOTED FOLLOW-UP INSP. REQUIRED			LICENSE NO. & EXP. DATE			
PO Box 248		.	HISTORY PREVIOUS		S VIOLA	TIONS:	X COMPLIANCE ORDE	R	1879 8/31/2016				
New Hope, PA 18938-0248			NOV'S X CORREC		ECTED	CTED		,	OPERATIONAL STATUS				
			1 CO'S UNCORR			RRECTE	RECTED CEASE ORDER			Active			
GENI	ERAL MINING INFORMATON:	Lar	rge ⊠ Small 10,000 □ 2			2.00	2,000 ☐ GP 105 ☐ GP 103 ☐ E		xpiration Date				
a. Are	a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Dolomite												
	en pit- ~2550' x ~'1100' x ~31						·		·				
h Fa	uipment-Use & Conditions: crushir	nalecros	anina nlant	e, seups	It plant: FE	l e- hau	i trucke: tr	ack excavators, packho	es water tr	ick- good c	ondition		
	ntract Miner: Yes 🔲 No 🛛 Nam		anny prant	s, aspira								No 🗀	
-	Approved Acres		Approve	d Pit Vo			d, Approved Blast Plan: Yes ⊠ No ☐ is there be Progress of Reclamation				Liability		
Mining	Area: 141 Support:		N/A yd³			Rec	Regraded 0 acres Topsoiled 0 acres			Current Bond			
	,				·····		Water Impoundment : Acres Approved 0						
Disturt	ped not planted:		Current		ıme	Acres Actual 0 Planted, Grasses 0 acres			\$465,850.00				
	Affected acres			/A yd³						Current Liability			
	Area: 141 Support:	1-3	ective Gra				Trees Required <u>0</u> ac. Planted <u>0</u> ac.			\$			
Distur	ped not planted;	Approv		yd³ Cui				1 criteria; 0 acres Approved/Affected		L			
<20 ft.	: ft ft >20<30		ft.		>30<40 ft.			t, >40<50 ft. ft	ft.	>50 ft.	ft,	ft,	
								NONCOAL					
- CI	OTANDADD							···		00	38-1		
Obs.	STANDARD		PC or Reg.	Viol.	Comp. Dæle	Obs.	Ai- Dave	STANDARD urces Protection		PC or Reg.	Viol.	Comp. Dale	
	Unauthorized Mining Mining License							ent Reclamation				-	
								g and Grading					
Signs and Markers Topsoll-Rem/Storage/Handling							Revegeta				급		
	Effluent Standard						Haul Roa					:	
	Diversions and Conveyance						General Safety						
Sediment Control Measures							Permit Conditions						
	Treatment Facilities						 	ry Mining Cessation		•			
Sedimentation Ponds								Limitations-Barriers					
Discharge Structures						Bench D	evelopment		_				
Dams, Ponds-Design/Const./Maint.		int.			133	in gold.	Permit Li	ine Setback	.,				
Water Monitoring-Ground/Surface		æ					Stability	Analysis					
Water Discharge-Underground Mine													
	Blasting Requirement				, .								
2015 the r	MENTS AND RECOMMENDATO i and Compliance Order No. 1 equested information. The Deployment of the Norwarded to NHCS via a sepa	5-5-04 partme	8-N(A) d mt's revie	ated No	vember 2	, 2015	; as New	Hope Crushed Stone	: Company	(NHCS)	has subr	nitted	
	•								***			:	
Down	Person Contacted Title Discharge/Seeps yes no												
Person Contacted Title Christina Cursley Accountant				Samples Collected ☐ yes ☐ no					•				
· · ·					_	les Collected		to	NT- 45	26			
Signature To be mailed				Investigator Signature Collector ID No. 4525 Employee ID No. 502407				,					
								A == 00 01-10	CII CII	throkee T	, 140° 20	240 /	

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report. White - District File Yellow - Permittee Pink - Inspector