

23

LAW OFFICES

SAMUEL J. ORR, III

1521 THIRD STREET

P. O. BOX 515

BEAVER, PA 15009

PHONE: (724) 774-5440

FAX NUMBER: (724) 774-7641

RECEIVED

AUG 07 2016

DEP SOUTHWEST REGION
ENVIRONMENTAL SERVICE

Administrative Record

August 5, 2016

PA Department of Environmental Resources
400 Waterfront Drive
Pittsburgh, PA 15222
ATTN: Ms. Annette Paluh

RE: Nick Crivelli Chevrolet
Former Westinghouse Electric Corporation Facility
Vanport Township, Beaver County
LRP No. 5-4-807-19073

Dear Ms. Paluh:

This will confirm our telephonic conversation of August 2, 2016 in which I advised you that Nick Crivelli and Nick Crivelli Chevrolet received a letter concerning the above matter. In our discussion, I advised that I was aware of the past history involving the TCE in the Vanport water supply in the late 1980's that resulted in a consent order between DEP and Westinghouse.

I also advised you that I previously engaged both Ed Monroe, an environmental engineer, at Gannett Fleming and Attorney Bruce Dice to assist us in dealings with DEP. I recall that Nick Crivelli agreed to permit test wells to be placed on his property. He advised me today that the wells are still there and that someone collects samples from the test site about every two months. We are unaware of who it is and he assumed that it was DEP.

I reviewed my file and I did find some reference to an access agreement between Westinghouse Electric and my client about ground water monitoring in the Vanport area. I am aware that a license agreement was prepared in 1990 and Mr. Crivelli may have an

Ms. Annette Paluh
August 5, 2016
Page 2

executed copy in his file. The ground water study was being conducted by Paul Rizzo Associates. I enclose a copy of a proposed subsurface exploration map. Frankly, we have heard nothing since that time.

I am also aware that there is also a monitoring well in the Beaver Cemetery but Beaver Cemetery personnel do not know whether the well is still being checked. Any correspondence to the Beaver Cemetery should be addressed to me as counsel for that entity.

As I indicated, this all took us by surprise because we believed that DEP was the moving party on the well monitoring. If you need to see Mr. Crivelli's file that ended with correspondence in 1993, please advise.

Very truly yours,




Samuel J. Orr, III, Esquire

Sjo/eo

Enclosure

cc: E. Stokan
G. Guenther
T. Goodwell
Admin Record
Region



LEGEND

- MW-5 (circle with dot) MONITORING WELL INSTALLED BY WESTINGHOUSE
- DER-10 (circle with dot) MONITORING WELL INSTALLED BY DER
- DER-9 (circle with dot) BORING PERFORMED BY DER
- MW-13 (circle with dot) MONITORING WELL INSTALLED BY VMA
- MW-14 (circle with dot) VMA PUBLIC WATER SUPPLY WELL
- MW-40 (circle with dot) PROPOSED MONITORING WELL
- S-43 (circle with dot) PROPOSED BORING

NOTES:

1. LOCATIONS OF SOME WELLS ARE APPROPRIATE PENDING AERIAL SURVEYING AND ADDITIONAL SURVEYING.
2. WELLS MW-13 AND MW-14 ARE SHALLOW IN DEPTH BUT MONITOR THE SOIL/ROCKOAK INTERFACE AND ARE THEREFORE GROUPED WITH THE DEEP WELLS.



FIGURE 6

PROPOSED SUBSURFACE EXPLORATIONS

WORK PLAN
VANPORT INVESTIGATION
PREPARED FOR

WESTINGHOUSE ELECTRIC CORPORATION
BEAVER, PENNSYLVANIA

DDP Paul C Rizzo Associates, Inc.